#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Pauline Tham Date: 18 Jul 2022

# **Preliminary Advice**

: SJX1229G Insured

Vehicle No

TP Vehicle Accident Date : SLF8836D

: 08/05/2022 No

Make : INFINITI Q50 Assignment Date: 11/05/2022

Date of : 04/07/2022 Est. Duration of : 3

Inspection Repair

Inspection At: WEARNES AUTOMOTIVE PTE LTD (LENG KEE)

28 LENG KEE ROAD SINGAPORE 159105

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 6,596.20 **Revised Amount** :S\$ 3,003.94 Check Items (Estimated) :S\$ 0.00 Total :S\$ 3,003.94

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

(	) The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.