

SMS 8459D.

TP FWD.

Header Shuttle.

Veron.

GK8 2103487

Front Bumper	Deformed	1050	✓
Front Bumper clips	m	30(SN).	✓
Front Bumper Side Holder RH	Dryd	38.50.	✓
Front Bumper Side Lamp RH.	2 { NP	245.50 +	
Front Bumper Side Lamp Cover RH	1 { NP	66.40 +	
Headlamp RH	1 ut	2250.40	✓
Headlamp Lower Bracket RH	1 Anhd	85.50	✓
Front Grille	2	363.40	X
Front Grille Logo	1 NP	65.40	X
Front Grille clips.	1 NEU	20(SN)	X

4215.50

SMS 8459D.

Front RH Fender	Dented	645.90 ✓
Front RH Fender Extension Panel	Repair	485.20 X
Front RH Fender Inner Shield	torn	189.30 ✓
Front RH Fender Inner Shield	new	30(SN) ✓
Front RH Fender Inner Shield	clips	800(SN) 489(SN)
Front RH Wheel Rim	Set	280(SN) X
Front RH Tyre	16 new	321.80 ✓
Front RH Lower Arm	Best	345.10 X
Front RH Shock Absorber	new	363.60 ✓
Front RH Knuckle Arm	Damaged	294.20 ✓
Front RH Wheel Hub	c/w Bearing	

5238.90
4191.12
S-N: 540

3755.10

SMS8459D.

Panel Beating

~~800~~ 600
~~820~~ 600

Spray Painting.

~~50~~ 30

Wiring

1570

~~155~~ 40

To spray tuff coat

~~350~~ 220

To remove front undercarriage.

~~150~~ 80

To perform wheel alignment.

2300

10,270.60

total: 6301.12

1/8 45K

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: