

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

T? Budget Direct.

Veron.

MIRS INNOVATE PTE LTD
5 LITTLE ROAD #03-01 CEMTEX IND
BUILDING
SINGAPORE 536983

TAX INVOICE

Repair Code : CLM17185

Date in : 07/05/2022

Vehicle Num. : SMN1181B

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104538838/1ZRY209230

Contact : 83892747

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	781.10	✓ 781.10
REAR BOOTLID 'ALTIS' EMBLEM	1	54.10	✓ 54.10
REAR BOOTLID 'COROLLA' EMBLEM	1	50.20	✓ 50.20
REAR BOOTLID 'LOGO' EMBLEM	1	58.50	✓ 58.50
REAR BOOTLID CHROME MOULDING <i>new</i>	1	253.70	+ 253.70
REAR BOOTLID HINGES L/R <i>new</i>	2	79.60	+ 159.20
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	4	7.00	+ 28.00
REAR BOOTLID LOCK STRIKER <i>new</i>	1	85.00	+ 85.00
REAR BOOTLID MECHANISM LOCK <i>Damaged</i>	1	379.20	✓ 379.20
REAR BOOTLID OPENER BUTTON SENSOR <i>new</i>	1	85.20	+ 85.20
REAR BOOTLID REFLECTOR L/R <i>cracked</i>	2	374.45	✓ 748.90
REAR BOOTLID WEATHER STRIP <i>at</i>	1	271.45	✓ 271.45
REAR BUMPER <i>Dented</i>	1	581.90	✓ 581.90
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	141.45	✓ 282.90
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	398.70	✓ 398.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Damaged</i>	2	165.00	✓ 330.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	2	198.00	✓ 396.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	2	121.10	✓ 242.20

60.

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MIRS INNOVATE PTE LTD
 5 LITTLE ROAD #03-01 CEMTEX IND
 BUILDING
 SINGAPORE 536983

Contact : 83892747

TAX INVOICE

Repair Code : CLM17185

Date in : 07/05/2022

Vehicle Num. : SMN1181B

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104538838/1ZRY209230

REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>Not in</i>	1	250.00	<i>x</i>	250.00
REAR BUMPER SIDE RETAINER L/R	<i>could</i>	2	65.00	<i>✓</i>	130.00
REAR END PANEL	<i>Distorted</i>	1	781.90	<i>✓</i>	781.90
REAR END PANEL ANTENNA SENSOR	<i>could</i>	1	192.20	<i>✓</i>	192.20
REAR END PANEL INNER TOP GARNISH	<i>could</i>	1	185.99	<i>✓</i>	185.99
REAR FENDER INNER TRIM L/R	<i>torn</i>	2	338.00	<i>✓</i>	676.00
REAR FLOOR PANEL TOP BOARD COVER	<i>torn</i>	1	485.10	<i>295</i>	485.10
REAR NUMBER PLATE LAMP L/R	<i>new</i>	2	48.00	<i>x</i>	96.00
REAR SPARE TYRE SCREW LOCK	<i>Dead</i>	1	78.00	<i>✓</i>	78.00
REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	<i>new</i>	2	25.50	<i>✓</i>	51.00
REAR TAILLAMP L/R	<i>could</i>	2	391.90	<i>✓</i>	783.80
REAR TAILLAMP LOWER BRACKET L/R	<i>could</i>	2	88.70	<i>✓</i>	177.40
Subtotal before discount					9,073.64
Percentage discount 25%					2,268.41
Sub-total 1					6,805.23
REAR BOOTLID CHROME MOULDING CLIPS - SET	<i>new</i>	1	30.00	<i>x</i>	30.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR BOOTLID NUMBER PLATE	<i>new</i>	1	25.00	<i>x</i>	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MIRS INNOVATE PTE LTD
5 LITTLE ROAD #03-01 CEMTEX IND
BUILDING
SINGAPORE 536983

Contact : 83892747

TAX INVOICE

Repair Code : CLM17185

Date in : 07/05/2022

Vehicle Num. : SMN1181B

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104538838/1ZRY209230

REAR BOOTLID NUMBER PLATE HOLDER	1	50.00	50.00
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR FENDER INNER TRIM CLIPS L/R - SET	2	50.00	100.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	40.00
Subtotal before discount			375.00
Percentage discount 0%			0.00
Sub-total 2			375.00
Parts-total			7,180.23

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

Labour Total

Parts & Labour Total

3,100.00

10,280.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Cj
h/s 12/05/22.

07 Days.

total: 808.18
h/s: 65K ✓