

COM TDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4429X

DATE 28.04.2022

MAKE/REG 15.08.2018

MODEL : HYUNDAI IONIQ G2

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>X repair</i>			\$459.40
1	REAR BUMPER BRACKET RH <i>X NN</i>			\$55.80
1	REAR WHEEL COVER RH <i>X NN</i>			\$346.40
1	REAR FENDER RH <i>X repair</i>			\$1,768.30
	SUB TOTAL			\$2,629.90
	LESS 20%			\$525.98
	DISCOUNTED TOTAL			\$2,103.92
1	REAR DOOR COMFORT APP <i>1 BL.</i>			\$80.00
				\$80.00
	Labour Charge			
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$800.00
	Remove/refix upholstery			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$2,000.00
	ESTIMATE TOTAL			\$4,103.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2 Days.

L/S

After repair photos.

Car Q19

04/5/22

11230

1180

-20%: 950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: