



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004441/Tqy3n2 Date: 03/06/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 7905G	Veh. Inspected	SHD 3566Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004811FR	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	11/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMHU096735	Colour	BLUE
	Odometer	606531 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/05/2022	Inspection Date	12/05/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	