

ASS. REC. BY: TaufikREF: Cs/MS22004441/Tay3.**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. 2022 22004811FR

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Always

Vehicle: IN / OUT

Veh No: SHD3566ZYr Regn: 2016 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 606531

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH LB4L UMM U 9675

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wasteke

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 12/5/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$2900, 2 days. (Red \$2461.06, 46%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 31/05 Typist

☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Rep. Formet: TPLump Sum / B.B.T: 2900

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHD3566Z

29.03.2022

MAKE REG. 08.12.2016

MODEL HYU- I40

CHIANG/ AILLIANZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REFLECTOR LH /RH		\$32.00	\$64.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	BOOTLID			\$2,609.80
1	BOOTLID LOWER GARNISH			\$227.90
2	BOOTLID HINGES LH/RH		\$142.30	\$284.60
1	BOOTLID MOULDING			\$85.00
1	BOOTLID CDRI			\$52.40
1	BOOTLID EMBLEM I40			\$67.90
				<b>\$4,694.20</b>
20.00%				<b>\$938.84</b>
<b>DISCOUNTED TOTAL</b>				<b>\$3,755.36</b>
1	BOTLID CITYAB & TEL NO. STICKER			\$60.00
1	REVERSE SENSOR			\$135.70
				<b>\$195.70</b>
<b>Labour Charge</b>				
Panel Beating				\$600.00
Spray Painting Charge				\$600.00
Remove/refix reverse sensor				\$60.00
Check lighting				\$60.00
Tuff Kote				\$90.00
<b>TOTAL LABOUR</b>				<b>\$1,410.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$5,361.06</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 2744749  
 WP' 12/5/2020 12pm  
 4/5 Rosny after repair  
 Tanpin 2744749  
 62 days

Date/Time: 09.05.2022 14:14 Page : 1

ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 4204586

JC NO.305515230

**COMFORT TRANSPORTATION PTE LTD**  
 CUSTOMER NO. 7010045  
 ADDRESS 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65508755  
 L. (R) (P) (O)


3COUNT CARD NO.

REGN NO.: <b>SHD3566Z</b>	MILEAGE
MAKE : <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL <b>I-40</b>	DATE/TIME IN <b>09.05.2022 09:30</b>
YR OF MANU. <b>08.12.2016</b>	TARGET DATE
CHASSIS CODE <b>KMHLB41UMHU096735</b>	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 08.05.2022  
 NATURE: 3P.08.05.2022

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: **SHD3566Z**                      **CHIANG**

Exit Pass

Vehicle No.: **SHD3566Z**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard