



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300626

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/02/2023
Reference CC6/CTI22004443/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3664Z
Insured Veh. GBD 4252T
Claim No. SNM22D203248/C02
Policy No. DMCVSNW00116782103
Accident Date 11/05/2022
Inspection Date 12/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22004443/Dpa3q2 Date: 02/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 4252T	Veh. Inspected	SHD 3664Z	
Policy No.	DMCVSNW00116782103	Coverage (\$)	0.00	
Claim No.	SNM22D203248/C02	Excess (\$)	0.00	
Assign From		Assign Date	12/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU096740	Colour	BLUE	
Odometer	467702 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2022	Inspection Date	12/05/2022	
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3664Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED	2,174.90	2,174.90
1	BOOTLID RUBBER	DEFORMED	96.50	96.50
2	BOOTLID HINGE (LH/RH) @\$284.60	NOT NECESSARY	569.20	-
1	BOOTLID LOCK UPPER	DAMAGED	114.90	114.90
1	BOOTLID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOTLID I40 EMBLEM (I40)	NECESSARY	67.90	67.90
1	BOOTLID 'H' EMBLEM	NECESSARY	63.10	63.10
1	BOOTLID CRDI PLATE	NECESSARY	52.40	52.40
2	BOOTLID LAMP (LH/RH) @\$1131.20	MTG CRACKED	2,262.40	1,131.20
2	LICENSE LAMP (LH/RH) @\$56.10	NOT NECESSARY	112.20	-
1	BOOTLID TRIMBOARD	SERVICEABLE	343.90	-
11	BOOTLID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID LOWER GARNISH CHROME(I40)	MTG CRACKED	385.30	385.30
1	REAR BUMPER	DISTORTED	1,106.00	553.00
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$160.60	BENT	321.20	321.20
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET	SERVICEABLE	35.60	-
1	REAR BUMPER SPONGE	TORN	119.50	119.50
1	REAR BUMPER UNDER COVER	SERVICEABLE	228.00	-
1	REAR BUMPER REFLECTOR LAMP (I40)	NOT NECESSARY	32.00	-
2	TAIL LAMP (LH/RH) @\$697.80	MTG CRACKED	1,395.60	1,395.60
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$453.00	NOT NECESSARY	906.00	-
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL LOWER	TO REPAIR SEE LABOUR	495.50	-
1	REAR PANEL GARNISH	MTG CRACKED	57.70	57.70
1	RADIATOR GRILLE H EMBLEM	SERVICEABLE	129.50	-
1	RADIATOR GRILLE	CRACKED	1,480.00	1,110.10

Report Ref No. CC6/CTI22004443/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	1,052.20	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	379.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	588.40	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	178.60	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$44.80	NOT NECESSARY	89.60	-
2	FRONT BUMPER BRACKET (LH/RH) @\$49.20	NOT NECESSARY	98.40	-
2	FRONT BUMPER RETAINER MOUNTING LH/RH @\$76.20	NOT NECESSARY	152.40	-
2	FRONT BUMPER GRILLE AIR DUCT (LH/RH) @\$126.20	NOT NECESSARY	252.40	-
1	HEADLAMP SUPPORT PANEL ASSY	NOT NECESSARY	907.40	-
2	HEADLAMP (LH/RH) @\$2776.00	MTG CRACKED	5,552.00	2,776.00
1	RADIATOR GRILLE	NOT NECESSARY	1,637.20	-
1	RADIATOR FAN BLOWER MOTOR ASSY	NOT NECESSARY	1,459.60	-
2	HORN UNIT (LH/RH) @\$73.80	NOT NECESSARY	147.60	-
1	AIRCON CONDENSER	NOT NECESSARY	947.80	-
	LESS 20% DISCOUNT		-5,402.38	-2,279.28
			21,609.52	9,117.12
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT LOGO STICKER (SN)	REPEATED	30.00	-
1	REAR NO PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT / I40 PLATE (SN)	DEFORMED	50.00	50.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	NOT NECESSARY	30.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
			420.70	265.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID LOCK LOWER ,REAR PANEL LOWER AND FRONT BUMPER COVER .		1,400.00	600.00
	SPRAY PAINTING CHARGE.		1,200.00	700.00

Report Ref No. CC6/CTI22004443/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHATRGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX RADIATOR .	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	DIAGNOSTIC RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			3,770.00	1,410.00
GRAND TOTAL			25,800.22	10,792.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CC6/CTI22004443/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3664Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3664Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3664Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

