

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 11-May-22
 INSURANCE: China Teping
 MODEL: HYUNDAI I40
 VEHICLE NO.: SHD 3664Z

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BOOTLID <i>Dent</i>	1	\$ 2,174.90	\$2,174.90
BOOTLID RUBBER <i>defined</i>	1	\$ 96.50	\$96.50
BOOTLID HINGE (LH/RH) <i>HH</i>	2	\$ 284.60	\$569.20
BOOTLID LOCK UPPER <i>Down</i>	1	\$ 114.90	\$114.90
BOOTLID LOCK LOWER <i>low</i>	1	\$ 31.70	\$31.70
BOOTLID I40 EMBLEM (I40) <i>src Hec</i>	1	\$ 67.90	\$67.90
BOOTLID 'H' EMBLEM <i>Hec</i>	1	\$ 63.10	\$63.10
BOOTLID CRDI PLATE <i>src Hec</i>	1	\$ 52.40	\$52.40
BOOTLID LAMP (LH/RH) <i>mainly crack 565-60x2</i>	2	\$ 1,131.20	\$2,262.40
LICENSE LAMP (LH/RH) <i>HH</i>	2	\$ 56.10	\$112.20
BOOTLID TRIMBOARD <i>src</i>	1	\$ 343.90	\$343.90
BOOTLID TRIMBOARD CLIPS (11 PCS) <i>HH</i>	1	\$ 11.00	\$11.00
BOOTLID LOWER GARNISH CHROME(I40) <i>low</i>	1	\$ 385.30	\$385.30
REAR BUMPER <i>distorted</i> <i>mainly crack</i>	1	\$ 1,106.00	\$1,106.00
REAR BUMPER REINFORCEMENT BRACKET LH/RH <i>HH</i>	2	\$ 160.60	\$321.20
REAR BUMPER REINFORCEMENT <i>crack</i>	1	\$ 428.40	\$428.40
REAR BUMPER CLIP (10 pcs) <i>Hec</i>	1	\$ 22.00	\$22.00
REAR BUMPER BRACKET <i>src</i>	1	\$ 35.60	\$35.60
REAR BUMPER SPONGE <i>turn</i>	1	\$ 119.50	\$119.50
REAR BUMPER UNDER COVER <i>src</i>	1	\$ 228.00	\$228.00
REAR BUMPER REFLECTOR LAMP (I40) <i>HH</i>	1	\$ 32.00	\$32.00
TAIL LAMP (LH/RH) <i>mainly crack</i>	2	\$ 697.80	\$1,395.60
TAIL LAMP QUARTER PANEL (LH/RH) <i>HH</i>	2	\$ 453.00	\$906.00
REAR PANEL <i>Dent</i>	1	\$ 526.70	\$526.70
REAR PANEL LOWER <i>low</i>	1	\$ 495.50	\$495.50
REAR PANEL GARNISH <i>mainly crack</i>	1	\$ 57.70	\$57.70
RADIATOR GRILLE H EMBLEM <i>src</i>	1	\$ 129.50	\$129.50
RADIATOR GRILLE <i>crack</i>	1	\$ 1,480.00	\$1,480.00
FRONT BUMPER COVER <i>low</i>	1	\$ 1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>HH</i>	1	\$ 379.20	\$379.20
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$ 588.40	\$588.40
Front Bumper Centre Grille <i>HH</i>	1	\$178.60	\$178.60
FRONT BUMPER BRACKET TOP (LH/RH) <i>HH</i>	2	\$ 44.80	\$89.60
FRONT BUMPER BRACKET (LH/RH) <i>HH</i>	2	\$ 49.20	\$98.40
FRONT BUMPER RETAINER MOUNTING LH/RH <i>HH</i>	2	\$ 76.20	\$152.40
FRONT BUMPER GRILLE AIR DUCT (LH/RH) <i>HH</i>	2	\$ 126.20	\$252.40
HEADLAMP SUPPORT PANEL ASSY <i>HH</i>	1	\$ 907.40	\$907.40
HEADLAMP (LH/RH) <i>mainly crack 1388-WX2</i>	2	\$ 2,776.00	\$5,552.00
RADIATOR <i>HH</i>	1	\$ 1,637.20	\$1,637.20
Radiator fan blower motor assy <i>HH</i>	1	\$ 1,459.60	\$ 1,459.60
HORN UNIT (LH/RH) <i>HH</i>	2	\$ 73.80	\$147.60
AIRCON CONDENSER <i>HH</i>	1	\$ 947.80	\$947.80

553.00

1395.60

1110.10

11,396.40

9,117.12

SUB TOTAL				\$27,011.90
LESS 20%				\$5,402.38
DISCOUNTED TOTAL				\$21,609.52
BOOTLID COMFORT LOGO & TEL NO. STICKER <i>Hee</i> SN	1	\$	30.00	\$30.00 ✓
BOOTLID COMFORT LOGO STICKER <i>Hee</i> SN	1	\$	30.00	\$30.00 X
REAR NO. PLATE <i>SN</i> SN	1	\$	25.00	\$25.00 X
REAR BUMPER REVERSE SENSOR <i>Don</i> SN	1	\$	135.70	\$135.70 ✓
REAR BUMPER ADVERTISEMENT LOGO <i>Hee</i> SN	1	\$	50.00	\$50.00 ✓
REAR BUMPER RUBBER MAT / I40 PLATE <i>Hee</i> SN	1	\$	50.00	\$50.00 ✓
FRONT NUMBER PLATE <i>HN</i> SN	1	\$	25.00	\$25.00 X
FRONT NO. PLATE TRIM COVER <i>HN</i> SN	1	\$	30.00	\$30.00 X
COOLANT <i>HN</i> SN	1	\$	45.00	\$45.00 X
SUB TOTAL				\$420.70
Labour Charge				
Panel Beating	1	\$	1,400.00	\$1,400.00 600/-
Spray Painting Charge	1	\$	1,200.00	\$1,200.00 700/-
Wiring Charge	1	\$	100.00	\$100.00 80/-
Tuff Kote	1	\$	100.00	\$100.00 40/-
Towing Charge	1	\$	80.00	\$80.00 40/-
Remove/Refix Reverse Sensor	1	\$	120.00	\$120.00 40/-
Remove/Refix Radiator	1	\$	90.00	\$90.00 40/-
Remove/Refix Aircon & Refill Gas	1	\$	130.00	\$130.00 40/-
Diagnostic & Resetting To Erase Fault Code	1	\$	550.00	\$550.00 1410.00
TOTAL LABOUR				\$3,770.00
ESTIMATE TOTAL				\$ 25,800.22
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				

12/05/2022 @ 1700hrs
NA *Hee*
L/S *Hee* 8 days.

Hee

LKK *Hee*

Hee

Check part prices.
Provide BV
before finalisation.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10,792.82

L/S 8,600/-

265.70/-

600/-
700/-
80/-
40/-
40/-
40/-
40/-
40/-

1410.00