

SMN8166A.

TP China.

Toyota CHR Hybrid

Xiao Teng.

ZYX102086539.

Rear Number Plate

Rear Number Plate Holder

Rear Number Plate Lamp x 02

Rear Bumper Distorted

Rear Bumper Clips. nr

Rear Bumper Side Holder x 02 nr

Rear Bumper Side Grille x 02 lt

Rear Bumper Side Grille Reflector x 02 ^{XL} ^{nr}

Rear Bumper Tow Cover Missing

Rear Bumper Lower Garnish. Distorted

Rear Bumper Reinforcement Bent

Rear Bumper Under Cover x 02. Behind

Reverse Sensor x 02 Damaged

Rear End Panel Distorted

Rear End Panel Antenna Sensor Damaged

30(SN) +

30(SN). +

$68.9 \times 2 = 137.80$ +

855.10 ✓

30(SN) ✓

$112.2 \times 2 = 224.40$ ✓

$187 \times 2 = 374$ ✓

$59 \times 2 = 118$ +

27.70 ✓

465.10 ✓

352.70 ✓

$189.20 \times 2 = 378.40$ ✓

$250 \times 2 = 500$ ✓

731.40 ✓

106.90 ✓

SMN8166A.

Rear End Panel Top Garnish	Behind	347.40	✓
Rear End Panel Top Garnish Clips.	per	20(SN)	✓
Rear End Panel Sealant	per	60(SN)	✓
Taillamp x 02	included	768.1 x 2 = 1536.20	✓
Taillamp Side Covers	lt	56.1 x 2 = 112.20	✓
Taillamp Panel x 02	Dented	285 x 2 = 570.	✓
Tailgate	Distorted	1112.50	✓
Tailgate Lock	Dryd	389.40.	✓
Tailgate Lock Cover	Behind	29.40	✓
Tailgate Lock Striker	per	105.50	+
Tailgate Outer Garnish	included	882.20	✓
Tailgate Outer Garnish Clips.	per	20(SN)	✓
Tailgate Damper x 02	2 NOS	291.2 x 2 = 582.40	+
Tailgate Hinge x 02	per	97 x 2 = 194.	+
Tailgate Inner Pull Pocket	Behind	38.40.	✓
Tailgate Glass Moulding	2 per	158.40.	✓
Tailgate Glass Sealant.	per	60(SN)	✓
Tailgate Weatherstripe	lt	371.40	✓

SMN 8166A.

Tailgate Wiper Arm. Not ne	93.40	x
Tailgate Wiper Motor Dargd	321.40	✓
Toyota Logo	72.20	✓
CHR Wording	55.60	✓
Hybrid Emblem.	121.40	✓
Rees Camera.	480(SN)	200(SN)
Video Recorder	580(SN)	x
Rees Fender x02	1219.1 x 2 = 2438.20	✓
Rees Fender Inner Trim x02	499.5 x 2 = 999	✓
Rees Fender Inner Trim Clips.	60(SN)	✓
Rees Fender Inner Shield x02	168.5 x 2 = 337	x
Rees Fender Inner Shield Clips.	40(SN)	x
Rees Fender Wheel Arc Garnish x02	195.2 x 2 = 390.40	✓
Rees Fender Wheel Arc Garnish Clips.	40(SN)	✓
Spore Tyre Panel	1350.40	x
Spore Tyre Panel Sealant	60(SN)	x
Spore Tyre Panel Insulation Pad	280(SN)	200(SN)

SMN 8166A.

Spare Tyre Panel Top Cover	Deformed	591.70. ✓
Tools Tray Centre	Deformed	371.80. ✓
Tools Tray Side x 02		$249.5 \times 2 = 499. ✓$
Rees Exhaust Pipe.	Dented	987.90. ✓
Rees Exhaust Pipe Mounting	HP nr	45. X
Rees Exhaust Pipe Heat Shield	Crumpled	110.90. ✓
Rees Exhaust Pipe Gasket	nr	45.40. ✓
Centre Exhaust Pipe.		
Rees Blind Spot Sensor x 02	HP nr	$1615 \times 2 = 3230. X$
Rees Blind Spot Sensor Bracket x 02	HP nr	$52.3 \times 2 = 104.60. X$
Rees Cross Member	HP nr	1455.80 X
Rees Lower Arm x 02		$497.5 \times 2 = 995. X$

14129.90

S.N. 890

110557.42

SMN 8166A.

Panel Beating	2000	1500
Spray Painting.	1800	1600
Wiring.	50	30
To spray tuff coat	200	100.
To remove reverse sensor	100	50
To remove rear camera.	100	50
To remove video recorder	100	50
To remove upholstery.	150	120
To transfer tailgate fittings.	150	100
To remove tailgate glass	180	120.
To remove fuel tank	150 X	4030
To remove rear. exhaust Pipe.	150	100.
To perform diagnostic test.	200	150
To perform wheel alignment test	150 X	
To dismantle rear undercarriage.	380 X	
Towing Fees.	60.	✓

SMN 8166A (Supplementary)

Tailgate Inner Trim Board crested 386-70 ✓

Tailgate Inner Trim Board Ups ^{re} 30(SN) ✓

Tailgate Lamp x02 crested 353.5 x 2 = 707. ✓
^{HEM}

Rear Bumper lower Greenish Reflector 145.40. X

To re-programme blind spot sensor

1093.70
820.27.

~~600~~ 250
S.N: 30
Labour: 250

Supplementary: 1100.27.

Total: 16617.69.

L/S: 13.3K.

08/07/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: