

TP A14.
Xiao Tony.

SNA1646J. 2019 Oct.
Volkswagen Golf. 1395 cc
WVWZZZAUZKW154009

Front RH. Door	Dented	1585 ✓
Front RH Door Lock	XP ✓	496. +
Front RH Door Weatherstripe.	✓	386. ✓
Front RH Door Glass Regulator	Dented	365 ✓
Front RH Door Glass Regulator Motor	XP ✓	385. +
Front RH Door Inner Trim Board	Cracked	786. ✓
Front RH Door Inner Trim Board clips.	✓	50(SN) ✓
Centre Pillar.	Regis	889. X.
Rear RH Door	Dented.	1480. ✓
Rear RH Door Lock	XP ✓	459. +
Rear RH Door Weatherstripe.	✓	382. ✓
Rear RH Wheel Rim.	XP ✓	800(SN) X.
Rear RH Tyre.	XP ✓	250(SN) X

4984

4485-60

SN-50

SNA 1646J.

Panel Beating

Spry Painting

Wiring.

To transfer front door fittings.

To transfer rear door fittings.

To perform wheel alignment.

To spray tuff coat

~~1000~~ 800
~~1000~~ 900

~~50~~ 30

~~150~~ 80

~~150~~ 80

150.X

80
~~150~~ 19.80

total: 6505.60

2/51 5.2K.

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5200