

From: **Gim Chye TAY (SCDF)** TAY_Gim_Chye@scdf.gov.sg
Subject: FW: ACCIDENT CLAIM FOR VEHICLE NUMBER SNE5045X AT 6 ENG KONG TERRACE ON 9 MAY 2022 (URGENT!!) SCDF Ref 2022 - 49
Date: 10 May 2022 at 10:01 PM
To: Meng Yan (LKK Auto) admin-d@lkkauto.com, Olivia Lau (LKKAuto) olivialau@lkkauto.com

GT

Dear Olivia and Yan,

Please conduct paper survey based on the quotation, thank you.

Yours sincerely,

Ralf Tay Gim Chye
Accident Claims Officer
Logistics Department
Singapore Civil Defence Force
91 Ubi Avenue 4, Singapore 408827
DID : +65 6848 3614 | Fax : +65 6848 3651
HP : +65 9743 5954



Singapore Civil Defence Force W [SCDF.gov.sg](https://www.scdf.gov.sg) FB [fb.com/SCDFpage](https://www.facebook.com/SCDFpage) IG [Instagram.com/mySCDF](https://www.instagram.com/mySCDF)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

RESTRICTED

ANNEX A

SINGAPORE CIVIL DEFENCE FORCE



Date: 9/5/2022

To Whom It May Concern,

**CORRESPONDENCE NOTICE
ACCIDENT INVOLVING SCDF VEHICLES**

1. If you wish to make any claim against the Government, please write to:

Accident Claims Officer,
Transport Services Branch, Logistics Department
HQ Singapore Civil Defence Force
91, Ubi Ave 4 Singapore 408827
Tel: 6848 3613
Fax: 6848 3644

2. In order to enable SCDF to assess your claims, you should submit the following documents to the above address:

- b. Appraiser Report with regard to the damages incurred;
- c. Detailed breakdown of the cost of repair; and
- d. Colour photographs of the damaged vehicle showing the damage.

3. Please take note that the above paragraphs are not and shall not be treated as acceptance by the Government of any liability whatsoever for any damages sustained as a result of the accident in which your vehicle and the SCDF vehicle are involved.

Thank you.

Yours faithfully,

**DIRECTOR LOGISTICS DEPARTMENT
FOR COMMISSIONER
SINGAPORE CIVIL DEFENCE FORCE**



A - 1
RESTRICTED



Police
report.pdf



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNE5045X

Foo Yoke Cheng

9a Eng Kong Terrace
Singapore 598981

Vehicle & Document Information

WIP No **56715**
Reg No/Reg Date **SNE5045X / 21/03/2022**
Date In/Mileage **/ 0**
Chassis No **W1K1771842J3287396**
Engine No **28291480692122**
Make/Model **MB/A 180 SALOON**
Colour/Trim **021 191 Cosmos Blac/ 041 101 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator				
WCV47824	CRDVCH	10/05/2022/ 13:13	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
A BPILAB								240.00 ✓
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES							0.05	800.00 ✓
RESPRAY REAR BUMPER								
A BPILAB								240.00 ✓
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								120.00 ✓
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								
M RH/ REAR LAMP COMBINATION					1.00	578.81	00.00	578.81 ✓
M REAR BUMPER LOWER TRIM					1.00	494.05	00.00	494.05 ✓
M RH/ REAR BUMPER LATERAL SUPPORT					1.00	135.49	00.00	135.49 ✓

3 days

ES

Not Applicable For Insurance Claim

Confirmed & accepted by

	Nett	2,608.35
7% GST on	2608.35	182.58

Authorized signatory and company stamp

Total Payable 2,790.93

Validity of this estimate is 34 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

 and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1







