



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNE5045X

Foo Yoke Cheng  
9a Eng Kong Terrace  
Singapore 598981

### Vehicle & Document Information

WIP No **56715**  
Reg No/Reg Date **SNE5045X / 21/03/2022**  
Date In/Mileage **/ 0**  
Chassis No **W1K1771842J3287396**  
Engine No **28291480692122**  
Make/Model **MB/A 180 SALOON**  
Colour/Trim **021 191 Cosmos Blac/ 041 101 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV47824	CRDVCH	10/05/2022/ 13:13	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				240.00 ✓
A BPIRES RESPRAY REAR BUMPER			0.05	800.00 ✓
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				240.00 ✓
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00 ✓
M RH/ REAR LAMP COMBINATION	1.00	578.81	00.00	578.81 ✓
M REAR BUMPER LOWER TRIM	1.00	494.05	00.00	494.05 ✓
M RH/ REAR BUMPER LATERAL SUPPORT	1.00	135.49	00.00	135.49 ✓

Not Applicable For Insurance Claim

3 days

Confirmed & accepted by

Nett **2,608.35**  
7% GST on **2608.35** **182.58**

Authorized signatory and company stamp

Total Payable **2,790.93**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG