

ASS. REC. BY:

REF:

A/G/ 22004448/Kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

04/23

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

STE 8307T

Yr Regn:

05, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

c.c

1498

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

145053

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMODE104180113800

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Road March

205/50ZR16

R: mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

2

mm

L/Bal.

6

mm

L/Bal.

2

mm

D.O.A.

11/5/22

D.O.I.

30/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

P. 105

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJE8307T
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000
ATTN: Motor Claim Department
WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SLH9091T

FAX: 64153727

Estimate No: ES2290529 ES2290529/WS
Date: 30 May 2022
Policy No: 5124325663
Veh Reg No: SJE8307T
Make/Model: MAZDA MAZDA 2 AT R
Chassis No: JM0DE10Y180113800
Engine No: ZY464286
Reg. Date: 09/05/2008

*Not Authorized
11 May @
Permy After Paim*

4-5 days

Estimate Repair Cost to Vehicle No :SJE8307T

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	875.00	1 PC	875.00	—
2 REAR BUMPER REINFORCEMENT	486.00	1 PC	486.00	7
3 REAR BUMPER CLIPS	4.50	6 PC	27.00	—
4 TAILLAMP LH	395.00	1 PC	395.00	—
5 REAR TAILGATE	896.00	1 PC	896.00	—
6 TAILGATE LOGO	47.00	1 PC	47.00	—
7 TAILGATE EMBLEM "MAZDA2"	35.00	1 PC	35.00	—
8 TAILGATE INNER LOCK	125.00	1 PC	125.00	7
9 TAILGATE INNER RUBBER	108.00	1 PC	108.00	X
10 REAR WINDSCREEN GLASS MOULDING	105.00	1 PC	105.00	—
11 REAR PANEL	398.00	1 PC	398.00	7
12 REAR PANEL TOP INNER GARNISH	102.00	1 PC	102.00	7
			3,599.00	
	Less 20%		719.80	2,879.20
Special Net				
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	—
14 REAR NUMBER PLATE	35.00	1 PC	35.00	—
15 ISET REVERSE SENSOR	200.00	1 PC	200.00	7
			275.00	275.00
Labour				
16 REMOVE AND REFIT REAR WINDSCREEN GLASS.	100.00	1 LA	100.00	✓
17 REMOVE AND REFIT REAR BUMPER ASSY, TAILLAMPS, TAILGATE, REAR SPOILER, REAR WIPER, REAR LOCK ASSY. TO CUT, WELD, RENEW REAR END PANEL AND REALIGN THE SAME.	800.00	1 LA	800.00	7
18 PUTTY AND RESPRAY ON REAR PANEL, REAR BUMPER, REINFORCEMENT, TAILGATE AND REAR AFFECTED	800.00	1 LA	800.00	600
19 RUSTPROOFING.	60.00	1 LA	60.00	?
			1,760.00	1,760.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 4,914.20
Add GST @ 7% 343.99
Total Amount Payable S\$ 5,258.19

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

B0001 / CHENG HOE MOTOR PTE LTD 11/05/2022
DATE & TIME: 11/05/2022 16:08 (SGT)
FILED BY: CHONG BENJ CHONG
ON: 1 (11/05/2022 16:08 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/05/2022 16:08 (SGT)
Date of Accident 11/05/2022 08:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information CTE TOWARDS SLE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJE8307T
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner TAN YONG CHUEN KENNETH (CHEN RONGQUAN)
NRIC No SXXXX351E
Email Address kenneth_joann_tan@yahoo.com.sg
Mobile Phone No (Phone) +65-97954085
Alternative Phone No +65-97954085

VEHICLE PARTICULARS

Manufacturer Mazda
Model MAZDA2 AT R
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1498


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5124325663
Cover Note Number 28/10/2021 -08/11/2022

DRIVER

Name of Driver JOANN LIM EN-MEI
NRIC No SXXXX080J

Sketch Plan



A = SJE8307T
 B = SLH 9091T
 mohd Taufik Abd Azusa
 hp: 9023 3715
 C = GBE1405J
 Bepary Muhammad Sumon
 G8178737P
 hp: 89156470

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 11/5/22 Time: 0845hrs. MS: NMC.

It was drizzling at that time. I was driving along CTE towards SLE on the 2nd lane. Unknown m/vehicle in front of me stop. I follow to stop behind. Out of sudden, I felt an impact on my rear. I came out of my car and realized I am involved in a chain accident of total 3 vehicles including mine.

No injuries on anyone.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: *[Signature]*
 NRIC/FIN No:

() Claim Own Policy () Claim Third Party () Reporting Only

11/5/22