

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0380/2022/JT
DATE : 13-May-22
WIP : 23719

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 19/5/22
YOUR INSURED VEH NO : GBG 620 A

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SOEDONO ADJI
ADDRESS : 83 PATERSON ROAD
#09-06
SINGAPORE 238549
TELEPHONE : HP +65 85004093
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 721005094
VEHICLE NO : SMA 3299 B
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 31/5/2021
ENGINE NO : CzD C39741
CHASSIS NO : WAUZZZF31M1115996
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-May-22
PLACE OF ACCIDENT : STEVENS ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 3299 B - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	\$ 1,000.00	550 ✓
SUB TOTAL LABOUR CHARGES		: \$ 3,480.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 3299 B - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT'S AND REAR WIPER ASSY.	S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	✓
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	150. ✓
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	✓
SUB TOTAL LABOUR CHARGES		:	\$ 1,920.00	

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 3299 B - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 2,800.00	100 ✓
7	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$ 3,000.00	1100. 1650.00 H.S.
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,392.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 3299 B - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regr</i>	1	\$ 2,308.00	+
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 132.00	+
3	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	+
4	FRONT BUMPER GRILLE LOWER COVER	1	\$ 58.00	+
5	FRONT BUMPER GRILLE - LH / RH	2	\$ 248.00	+
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	+
7	FRONT BUMPER SPOILER <i>new</i>	1	\$ 426.00	+
8	FRONT BUMPER BRACKET <i>new</i>	1	\$ 24.00	+
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>AKA RH cut</i>	2	\$ 342.00	177 136.40
10	RADIATOR GRILLE <i>encl'd</i>	1	\$ 1,594.00	✓ 1275.20
11	RADIATOR GRILLE STRIKER PLATE <i>encl'd</i>	1	\$ 271.00	✓ 216.80
12	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 47.00	✗
13	RADIATOR GRILLE BRACKET <i>new</i>	1	\$ 46.00	✗
14	RADIATOR GRILLE SECURING STRIP <i>new</i>	1	\$ 37.00	✗
15	FRONT CAMERA <i>new</i>	1	\$ 1,261.00	+
16	FRONT BUMPER REINFORCEMENT BEAM <i>Revised</i>	1	\$ 974.00	✓ 718.80
17	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 114.00	+
18	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 86.00	+
19	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 137.00	+
20	CAUTION STICKER <i>new</i>	1	\$ 16.00	+
SUB TOTAL SPARE PARTS			\$ 8,575.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 3299 B - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AIR COND STICKER	1	\$	9.00	+
22	FRONT PARKING AID SENSOR	2	\$	530.00	+
23	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00	+
24	HEADLIGHT MOUNTING - LH / RH	2	\$	264.00	✓ 210.40
25	HEADLIGHT - LH / RH	2	\$	11,904.00	+
26	LIFT CYLINDER - LH / RH	2	\$	462.00	x
27	LIFT CYLINDER HOSE	1	\$	92.00	x
28	RADIATOR AIR GUIDE OUTER - LH / RH	2	\$	86.00	✓ 34.08
29	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	96.00	+
30	FRONT WHEEL ARCH COVER - LH / RH	2	\$	566.00	✓ 452.00
SUB TOTAL SPARE PARTS		:	\$	14,019.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 3299 B - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Dented</i>	1	\$	1,738.00	✓ 1390.40
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$	220.00	+
3	REAR BUMPER SPOILER <i>Dented</i>	1	\$	510.00	✓ 408.00
4	REAR BUMPER TOWING EYE <i>new</i>	1	\$	48.00	+
5	REAR BUMPER BRACKET <i>Damaged</i>	1	\$	53.00	✓ 42.40
6	REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2	\$	92.00	+
7	TAIL LIGHT INNER - LH / RH <i>new</i>	2	\$	2,060.00	+
8	TAIL LIGHT TRIM INNER - LH / RH	2	\$	68.00	+
9	REAR BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$	693.00	✓ 554.40
10	REAR BUMPER HOLDING STRAP - CENTER <i>Not nec</i>	1	\$	120.00	X
11	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	142.00	+
12	REAR PARKING AID SENSOR	2	\$	530.00	+
13	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$	10.00	+
14	REAR LID <i>Dented</i>	1	\$	3,767.00	✓ 3013.60
15	REAR PACKING ADHESIVE <i>new</i>	1	\$	21.00	✓ 16.72
16	REAR LID ATTACHMENT PARTS <i>new</i>	1	\$	393.00	+
17	REAR LID LOCK	1	\$	292.00	+
18	REAR LID LOCK COVER <i>new</i>	1	\$	8.00	+
19	REAR LID STRIKER PLATE <i>new</i>	1	\$	74.00	+
20	REAR LID LOCK ACTUATOR	1	\$	1,478.00	+
SUB TOTAL SPARE PARTS			:	\$ 12,317.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 3299 B - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR LID FLAP GASKET <i>Nec.</i>	1	\$ 229.00	✓	182.80
22	AUDI EMBLEM <i>3 nec</i>	1	\$ 144.00	✓	114.80
23	Q3 EMBLEM	1	\$ 104.00	✓	82.80
24	REAR WINDSCREEN <i>den</i>	1	\$ 1,064.00	✓	851.20
25	PRIMER <i>den</i>	1	\$ 22.00	✓	17.36
26	REAR LID TOP SPOILER - LH / RH <i>Nec.</i>	2	\$ 470.00	✗	375.20
27	REAR LID GASKET CLIP <i>3 nec</i>	2	\$ 16.00	+	
28	REAR END PANEL TRIM	1	\$ 213.00	+	
29	REAR WHEEL ARCH COVER - LH / RH <i>den</i>	2	\$ 566.00	✓	452.00
30	LED LICENCE PLATE <i>nec</i>	2	\$ 113.00	+	
31	REAR LID TRIM PANEL - LOWER <i>den</i>	1	\$ 541.00	✗	
32	REAR WINDSCREEN SEALANT <i>den</i>	S/N	\$ 200.00	✓	
33	FRONT NO PLATE <i>Denial</i>	S/N	\$ 60.00	✓	
34	REAR NO PLATE <i>den</i>	S/N	\$ 60.00	✗	
35	SUNDRIES <i>Nec.</i>		\$ 500.00	✓	211.60
TOTAL SPARE PARTS (FRONT & REAR)			\$ 39,213.00		
TOTAL LABOUR CHARGES (FRONT & REAR)			\$ 11,392.00		
GRAND TOTAL			\$ 50,605.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Adrian*
: *19/05/22*

:
: *not authorised, 08 days*
: *10 days. S.S.*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/TP/0380/2022/JT
Date 28-Jun-22
Service Advisor CHANG
Pages 1 of 1
Regn No SMA 3299 B
Model No AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

1	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	\$ 1,600.00	\$ 1,600.00	✓
2	TO CUT OUT AND WELD REAR END PANELLING.		\$ 2,400.00	\$ 1,000.00	✓

Parts

1	REAR CROSS PANEL		\$ 329.00	\$ 262.80	✓
2	REAR LID BUNGS	4	\$ 132.00	\$ 105.60	✓
3	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00	✓
4	CAVITY WAX	S/N	\$ 140.00	\$ 140.00	✓
5	STONE CHIP	S/N	\$ 180.00	\$ 180.00	✓
6	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00	✓

GRAND TOTAL \$ 5,241.00 \$ 3,748.40

For Premium Automobiles Pte Ltd

Authorised Signature