

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004453/APA3Q2**Date:** 14/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900230868
Claimant Vehicle No :	SLU819C	Insured Vehicle No :	SMP8731H
Date of Loss:	04/05/2022	Nature of Claim:	TP
		Claim No:	2289489092SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU819C	Engine No:	2ZR1989241
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400026134
Reg. Date:	22/11/2017 (Man. Year: 2017)	Odometer:	114978 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,368.27	5,682.20	4,686.07	45.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,020.00	2,230.00	2,790.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,388.27	7,912.20	7,476.07	48.58
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	15,388.27	6,300.00	9,088.27	59.06
+ GST 7.00/7.00% (\$\$)	1,077.18	441.00	636.18	59.06
Nett Amount (\$\$)	16,465.45	6,741.00	9,724.45	59.06
+ Car Rental (8.0 x \$S\$100.00/day) (\$\$)		800.00		
Nett Liability (\$\$)		7,541.00		
Global Sum Settlement (\$\$)		7,500.00		

INSPECTION

Date of Assignment:	05/05/2022		
Date Inspected:	05/05/2022	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,345.20 FL	*989.00 FL
2	1		*TAILGATE BADGE	Not Necessary	98.60 FL	*- FL
3	1		*TAILGATE EMBLEM (PRIUS)	Necessary	92.50 FL	*92.50 FL
4	1		*TAILGATE EMBLEM (HYBRID)	Necessary	91.70 FL	*91.70 FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	891.20 FL	*- FL
6	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
7	2		*TAILGATE OUTER GARNISH SIDE COVER	Not Necessary	192.00 FL	*- FL
8	2		*TAILGATE STOPPER	Not Necessary	56.00 FL	*- FL
9	1		*TAILGATE POCKER HANDLE	Not Necessary	65.20 FL	*- FL
10	1		*TAILGATE INNER TRIM	Cracked	398.50 FL	*398.50 FL
11	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
12	1		*TAILGATE INNER LOCK	Damaged	298.70 FL	*298.70 FL
13	1		*TAILGATE AUTO LOCK ACTUATOR	Not Necessary	191.50 FL	*- FL
14	1		*TAILGATE LOCK CATCH	Not Necessary	48.20 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	298.50 FL	*298.50 FL
16	1		*TAILGATE TOP WINDSCREEN MOULDING	Necessary	98.60 FL	*98.60 FL
17	1		*TAILGATE TOP WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
18	1		*TAILGATE BOTTOM WINDSCREEN MOULDING	Necessary	97.20 FL	*97.20 FL
19	2		*TAILGATE BOTTOM WINDSCREEN INNER SEAL	Necessary	130.00 FL	*130.00 FL
20	1		*REAR BUMPER	Deformed	1,294.30 FL	*823.00 FL
21	2		*REAR BUMPER SIDE RETAINERS	Necessary	250.60 FL	*250.60 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
23	2		*REAR BUMPER REFLECTORS	Cracked	197.20 FL	*197.20 FL
24	2		*TAILLAMPS	Cracked	1,016.40 FL	*1,016.40 FL
25	2		*TAILLAMPS INNER SEALER	Not Necessary	76.00 FL	*- FL
26	2		*TAILLAMPS LOWER BRACKETS	Not Necessary	130.60 FL	*- FL
27	2		*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*20.00 FL
28	1		*REAR FENDER	Not Necessary	986.50 FL	*- FL
29	1		*REAR FENDER INNER TRIMS (RH)	Cracked	425.60 FL	*425.60 FL
30	2		*REAR FENDER INNER COWLING	Not Necessary	165.30 FL	*- FL
31	2		*REAR FENDER AIR DUCTS	Not Necessary	172.60 FL	*- FL
32	1		*END PANEL	Dented	679.80 FL	*679.80 FL
33	1		*END PANEL TOP TRIM	Cracked	198.60 FL	*198.60 FL
34	1		*SET END PANEL TOP TRIM CLIP	Necessary	30.00 FL	*20.00 FL
35	1		*REAR FLOOR PANEL TOP BOARD	Deformed	398.70 FL	*398.70 FL
36	1		*REAR FLOOR PANEL TOOL BOX	Cracked	598.60 FL	*495.00 FL
37	1		*REAR FLOOR PANEL	Repair	805.30 FL	*- FL
38	1		*REAR EXHAUST SILENCER	Not Necessary	794.00 FL	*- FL
39	2		*REAR EXHAUST MOUNTINGS	Not Necessary	92.00 FL	*- FL
40	1		*REAR EXHAUST GASKET	Not Necessary	52.00 FL	*- FL
41	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
42	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
43	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
44	1		*SET FLOOR PANEL INSULATOR PAD	Not Necessary	120.00 FS	*- FS
45	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,617.70	7,469.60
- List Item Discount on L Items 25.00/25.00% (\$)	3,249.43	1,787.40
Total Parts (\$)	10,368.27	5,682.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	850.00
2	SPRAY PAINTING	New	2,000.00	850.00
3	CHECK WIRING ON TAILLAMPS	New	100.00	30.00
4	ANTI RUST	New	120.00	60.00
5	REMOVE AND INSTALL UPHOLSTERY	New	100.00	80.00
6	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
7	REMOVE AND INSTALL TAILGATE PARTS	New	100.00	80.00
8	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
9	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	50.00
10	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	50.00
11	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (S\$)			5,020.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >