

MAX MOTORS

TP Chinn.
Xiao Tong.

1 Kaki Bukit Ave 6, #01-98, AutoBay @ Kaki Bukit, Singapore 417883

H/P: 9025 1807

Email: qinding@maxmotors.com.sg

Vehicle number: SKZ3976Y

Vehicle Made & Model: HONDA VEZEL

Qty	List Items	Amount \$
1	Tailgate <i>Dented</i>	1,287.10 1100
1 set	Tailgate glass moulding <i>new</i>	121.20 x
1	Tailgate outer garnish <i>new</i>	391.40 x
1	Tailgate emblem 'H' <i>new</i>	48.60 x
1	Tailgate emblem "VEZEL" <i>new</i>	58.60 ✓
2	Tailgate lamps - L/R @ 470.30 <i>new</i>	940.60 x.
1	Tailgate inner lock <i>Damaged</i>	280.60 ✓
1	Tailgate inner trim board <i>cracked.</i>	486.90 305
1	Tailgate inner pull pocket <i>new</i>	89.90 x
1	Tailgate w/strip <i>lit</i>	198.70 ✓
2	Tailgate dampers - L/R @ 140.40 <i>new</i>	280.80 x
2	Tailgate stoppers @ 12.60 <i>new</i>	25.20 ✓
2	Taillamps - L/R @ 528.10 <i>new</i>	1,056.20 x.
1	Rear bumper <i>Debond</i>	891.60 745.
2	Rear bumper reflectors - L/R @ 171.20 <i>cracked.</i>	342.40 242
2	Rear bumper sides - L/R @ 241.60 <i>new</i>	483.20 x
2	Rear bumper side retainers - L/R @ 48.60 <i>new</i>	97.20 ✓
1	Rear end panel <i>Dented</i>	759.10 585
1	Rear end panel trim <i>Debond</i>	241.20 ✓
1	Rear exhaust silencer <i>new</i>	547.60 x
1	Rear exhaust insulator <i>new</i>	130.20 x.
1	Rear floor board <i>new</i>	370.60 x
1	Rear floor tool tray <i>new</i>	361.80 x
1	Rear floor panel <i>new</i>	965.80 x
1	Rear floor panel undercover <i>Debond</i>	281.60 ✓
2	fender wheel arch garnishes @ 341.20 <i>new</i>	682.40 x
2	fender inner trim boards - L/R @ 641.20 <i>new</i>	1,282.40 x.
1	smart keyless antenna <i>new</i>	191.20 132.

Vehicle number: SKZ3976Y

Vehicle Make & Model: HONDA VEZEL

1 Rear smart keyless buzzer *2y2*

~~196.80~~ *95*

Sub-total 13,090.90

Less 20% 2,618.18

Total List 10,472.72

Special Nett Items

1 set Tailgate glass sealant

~~80.00~~ *60*

1 set Tailgate glass foam tape *}m*

~~65.00~~ *40*

1 Rear bumper chrome plate *Distorted*

~~450.00~~ *350*

1 Rear bumper lower spoiler *Defend*

~~650.00~~ *500*

1 set Rear bumper clip *Neu*

~~45.00~~ *30*

1 set Rear reverse sensor - 4Pcs *Damaged*

~~420.00~~ *300*

1 Rear reverse camera *Not Nec*

~~480.00~~ *X*

1 set Tailgate Surround Moulding *NEC*

Total Special Nett 2,190.00

300 200

Labour charges

To check rear electrical wiring

~~80.00~~ *30*

To remove, refix tailgate glass

~~180.00~~ *120*

To remove, refix rear interior trims to assist repair

~~150.00~~ *60*

To remove, refix rear reverse sensor / camera

~~120.00~~ *100*

Transfer & reinstall tailgate componets to new tailgate

~~150.00~~ *80*

To respray undercoating

~~60.00~~ *✓*

To respray painting and etc

~~1,300.00~~ *800*

Panel beating, cut, weld remove & replacing above parts

~~1,500.00~~ *800*

Total Labour 3,540.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary details of the work done is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 16,202.72

Total: 6619.52

L/s: 5.3K

06 Days.

5.3K