

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0366/2022/JT
DATE : 11-May-22
WIP : 23014

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

4 days - ok - Johnny Boo

5-Oct-22

OWNER'S NAME : MR CHEONG KWN CHOONG
ADDRESS : 29 YISHUN CENTRAL 1
#09-61
SINGAPORE 768804
TELEPHONE : HP +65 96648382
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100327724-09
VEHICLE NO : **SKJ 3303 Z**
MODEL CODE : AUDI A7 SB 2.0 TFSI
MODEL YEAR : 16/1/2013
ENGINE NO : CHV 017209
CHASSIS NO : WAUZZZ4G3DN0808795
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Apr-22
PLACE OF ACCIDENT : ALONG KUALA LUMPUR TO IPOH HIGHWAY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKJ 3303 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,672.00	\$ 1,722.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 3303 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,591.00	\$	2,872.80
2	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 248.00		
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 230.00		
4	FRONT BUMPER FIXING PARTS	1	\$ 287.00		
5	FRONT BUMPER AIR GUIDE GRILLE	1	\$ 171.00		
6	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 237.00	\$	189.20
7	FRONT BUMPER SPOILER	1	\$ 276.00		
8	RADIATOR GRILLE	1	\$ 1,578.00		
9	QUATTRO EMBLEM	1	\$ 111.00		
10	RADIATOR GRILLE COVER	1	\$ 31.00		
11	LICENCE PLATE HOLDER	1	\$ 479.00		
12	FRONT BUMPER GRILLE - LH	1	\$ 283.00	\$	226.40
13	FRONT BUMPER END CAP - LH	1	\$ 65.00	\$	51.92
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 111.00		
15	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 927.00		
16	FRONT BUMPER TOP COVER	1	\$ 137.00		
17	FRONT BUMPER GUIDE PIECE - LH	1	\$ 50.00		
18	FRONT BUMPER BRACE - LH	1	\$ 34.00		
19	FRONT BUMPER SUPPORT - LH	2	\$ 29.00		
20	FRONT BUMPER POP RIVET	4	\$ 7.00		
SUB TOTAL SPARE PARTS		:	\$ 8,882.00	\$	3,340.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKJ 3303 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 3,340.32
21	AIR COND STICKER	1 \$	34.00	
22	HORN - LH	1 \$	197.00	
23	HORN SUPPORT- LH	1 \$	53.00	
24	FRONT PARKING AID SENSOR	1	TBC	
25	FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER	4 \$	6.00	
26	FRONT WHEEL HOUSING LINER - LH	1 \$	299.00	
27	FRONT WHEEL SPOILER - LH	1 \$	414.00	\$ 331.20
28	HEADLIGHT MOUNTING - LH	1 \$	132.00	
29	HEADLIGHT - LH	1 \$	3,769.00	
30	HEADLIGHT MOUNTING UPPER - LH	1 \$	131.00	
31	LIFT CYLINDER	1 \$	259.00	\$ 207.20
32	LIFT CYLINDER HOSE	5 \$	215.00	
33	FRONT FENDER STONE GUARD FILM - LH	1 \$	128.00	
34	FRONT NO PLATE	S/N \$	60.00	
35	Added parts - see attached	\$	38.00	\$ 29.76
36	SUNDRIES	\$	350.00	
TOTAL SPARE PARTS			\$ 14,967.00	\$ 3,908.48
TOTAL LABOUR CHARGES			\$ 4,672.00	\$ 1,722.00
GRAND TOTAL			\$ 19,639.00	\$ 5,630.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-31/08/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0366/2022/JT 28-Jun-22 CHANG 1 of 1 SKJ 3303 Z AUDI A7 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	WASHER HOSE ELBOW FITTING	\$ 33.00	\$ 26.08
2	WASHER HOSE CLAMP	\$ 5.00	\$ 3.68
GRAND TOTAL		\$ 38.00	\$ 29.76

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT