

ASS. REC. BY:

REF:

ASM/22004463/Kqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1000

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

81436

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 755B

Yr Regn:

06.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo XC60

C.C.

1989

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

80860

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YV1074060112155896

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/45R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

4/3/22

D.O.I.

13/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/5/21 PM @ 1550L Cuhw (Red 1405, 4870)

18/5/22 @ 10.33am revised to Lynn Khong via Smart Claims.

Date/Time, File Pass to?

1) 08/5/2022

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Smart Claims - TP

Lump Sum / I.B.F. (\$

1550

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

GST No : 200600989k

AXA Insurance Singapore Pte Ltd

Motorcar Claim Department

Attn Claim Officer

Estimate Repair

Date : 13/5/2022

Accident Involving SMS755P & SHD4203P On 04/03/2022

SMS755P

Volvo

Item	Descriptions	Amount
1	Front Bumper <i>1845.00</i>	<i>Bm / car</i> \$ 2,350.00 ✓

Total For Parts (Less 10%) \$ 2,350.00

S/N Item (s)

1	Bumper Clips - 1 Set	\$ <i>35</i> 35.00 ✓
---	----------------------	----------------------

Total For S/N \$ 35.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	
	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 220.00 <i>200</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 350.00 <i>240</i>

\$ 570.00

Total For Parts & Labour \$ 2,955.00

Ready Auto Care Pte Ltd

Sulynn - 96606551

No Of Days For Repair **2 Days** ✓



*NOT authorized
11hr @ 1550/h
Running After Pain*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: