

ASM

Shian Chan

Taufik Survey on 17/5/2022



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ6736Z 2022 Alphard PI

No	Qty	Parts Description	Estimated Parts Price
100 1	1	Rear bumper assy	1344 \$ 1,517.30 de
2	1	Rear bumper left bracket	\$ 98.00 ana
3	1	Rear bumper right bracket	\$ 98.00 X un
4	1	Rear left side retainer	\$ 95.00 ana
5	1	Rear right side retainer	\$ 95.00 X un
3	1	Rear bumper tow cover	\$ 68.00 de
60 5	1	Bumper reflector left	110 \$ 225.00 ana
6	1	Bumper reflector right	\$ 225.00 X un
7	1	Rear left side cover trim-side guard cover	\$ 283.50 de
8	1	Bumper lower side trim	\$ 168.30 de
9	1	Lower cover trim	\$ 228.50 X un
10	1	Sensor cable	\$ 850.00 X un
11	2	Sensor with bracket at left and middle @245	\$ 600.00 ana 400 + 190
12	1	Lower tray at left area	\$ 285.00 X un
13	1	Tailgate	\$ 2,200.00 R X
14	1	Tailgate rubber	\$ 280.00 X un
15	1	Rear end panel / side panel	\$ 950.00 R p
16	1	Reinforcement / side support metal	450 \$ 550.00 bt
17	1	Alphard logo	\$ 105.00 ana
18	1	Toyota logo	\$ 95.00 ncc X
19	1	Rear left light	\$ 1,800.00 X un
20	1	Rear tailgate light	\$ 1,500.00 X un
		Parts sub-total	\$ 12,316.60

25% 3116.80 + 755
25% 2237.60 2528.85



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ6736Z 2022 Alphard PI

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 100.00 50 x 2
2	8	Rear side bracket clips square clips	\$ 80.00 40
3	8	Rear end lower panel top garnish clips	\$ 80.00 X
4	1	Rear side panel sealant	\$ 120.00 X 30V
5	8	Rear side trim clips	\$ 80.00 X
6	6	Tailgate garnish clips	\$ 80.00 X
7	10	Rear lower trim clips	\$ 60.00 X
8	1	Rear no plate with garnish	\$ 80.00 X
		Sub total special nett	\$ 680.00 50 x 30



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ6736Z 2022 Alphard PI

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 2,000.00 550✓
2	To putty and spray painting behind portion.	\$ 2,000.00 600✓+80
3	To check wiring and focus behind lights	\$ 80.00 30 X AM 30✓
4	To apply anti rust proofing to front affected area.	\$ 200.00 30X
5	To remove and install undercarriage parts.	\$ 150.00 Xnn
6	To balance the wheel.	\$ 80.00 Xnn
7	To conduct wheel alignment.	\$ 120.00 Xnn
8	Ceremic coating for affected area	\$ 150.00 Xnn
9	Remove and install winscreen facillite works	\$ 150.00 nix
10	Rear water test	\$ 120.00 Xnn
11	Remove and install tailgate internal and side trims and light	\$ 250.00 60✓
12	Check rear bumper wiring	\$ 100.00 30X Rpt.
13	Computer reset system / after accident	\$ 250.00 Xnn
Total repair cost :		5,650.00 1240+80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification (s) to vehicle
- Supplementary work to be done is surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495749
WP 17/5/22 C1/An
L/S Rony after repair
Tanfer C. Khantun
04 days
2,528.85
80
132.0
3,928.85
L/S \$3150
04 days
X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification (s) to vehicle
- Supplementary work to be done is surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: