

Hth Kenneth
Cheng Hoe Motor Pte Ltd *KV*

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKX7680J

TP/CHINA

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62221033

ATTN: Motor Claim Department

Not Authorized

WS Ref: TP CHINA

Claim Type: Third Party

Accident Date: 10/05/2022

TP Veh Reg No: PC4563K

Claim No: ES2290475

Estimate No: ES2290475/YISHUN

Date: 12 May 2022

Policy No:

Veh Reg No: SKX7680J

Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4A/T

Chassis No: JMYSRCY2A8U007002

Engine No: 4A910082765

Reg. Date: 28/08/2008 *2018*

Recovery B4 point
12 days

Estimate Repair Cost to Vehicle No : SKX7680J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	250.00	1 PC	<i>R</i> 250.00	✓
2 REAR BUMPER LOWER PROTECTOR	450.00	1 PC	<i>CM</i> 450.00	✓
3 REAR BUMPER SIDE RETAINER RH	15.00	1 PC	<i>CM</i> 15.00	✓
4 REAR BUMPER INNER GARNISH RH	12.00	1 PC	<i>Pu</i> 12.00	X
5 REAR BUMPER CLIP	2.00	6 PCS	<i>R</i> 12.00	✓
6 REAR BUMPER CENTRE INNER GARNISH	45.00	1 PC	<i>R</i> 45.00	✓
7 REAR WINDSCREEN GLASS MOULDING	480.00	1 PC	<i>mid R</i> 480.00	✓
8 REAR BOOT	380.00	1 PC	<i>R</i> 380.00	✓
9 REAR BOOT LOGO	28.00	1 PC	<i>R</i> 28.00	✓
10 REAR BOOT EMBLEM - ATTRAGE	18.00	1 PC	<i>R</i> 18.00	✓
11 REAR BOOT EMBLEM - MIVEC	42.00	1 PC	<i>R</i> 42.00	✓
12 REAR BOOT INNER LOCK	100.00	1 PC	<i>R</i> 100.00	✓
13 REAR BOOT INNER RUBBER	68.00	1 PC	<i>D/S</i> 68.00	✓
14 REAR BOOT OUTER MOULDING	175.00	1 PC	<i>R</i> 175.00	✓
15 REAR BOOT HINGE LH	90.00	1 PC	<i>R</i> 90.00	✓
16 TAILLAMP	128.00	2 PCS	<i>N/S Bu</i> 256.00	✓
17 TAILLAMP PANEL LH	55.00	1 PC	<i>R</i> 55.00	✓
18 REAR CENTRE PANEL	220.00	1 PC	<i>R</i> 220.00	✓
19 REAR CENTRE PANEL INNER TOP GARNISH	45.00	1 PC	<i>R</i> 45.00	✓
20 REAR SPARE TYRE TOP BOARD	105.00	1 PC	<i>CM</i> 105.00	✓
21 REAR SMART KEY SENSOR	65.00	1 PC	<i>R</i> 65.00	✓
22 REAR LH FENDER	460.00	1 PC	<i>Bu</i> 460.00	✓
23 REAR LH FENDER INNER SHIELD	24.00	1 PC	<i>CM</i> 24.00	✓
24 REAR LH FENDER INNER GARNISH	118.00	1 PC	<i>Dehun</i> 118.00	✓
25 REAR SPARE TYRE COMPARTMENT	500.00	1 PC	<i>R</i> 500.00	X
				4,013.00
Special Net				
26 REAR BOOT TOP GARNISH SPOILER	280.00	1 PC	<i>CM</i> 280.00	✓
27 REVERSE SENSOR	200.00	1 SET	<i>R</i> 200.00	✓
28 REVERSE CAMERA	350.00	1 SET	<i>R</i> 350.00	✓
29 REAR WINDSCREEN GLASS GUM	40.00	1 PC	<i>R</i> 40.00	✓
				870.00

87546.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPIING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department

Claim No: ES2290475
Estimate No: ES2290475/YISHUN
Date: 12 May 2022
Policy No:
Veh Reg No: SKX7680J
Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4A/T
Chassis No: JMYSRCY2A8U007002
Engine No: 4A910082765
Reg. Date: 28/08/2008

WS Ref: TP CHINA
Claim Type: Third Party
Accident Date: 10/05/2022
TP Veh Reg No: PC4563K

Estimate Repair Cost to Vehicle No : SKX7680J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
30 TOWING BY OWNER	0.00	1 LA	0.00	
31 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
32 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR LH FENDER, REAR PANEL, REAR COMPARTMENT, LH TAILLAMP PANEL, TO STRAIGHTEN, KNOCK & REPAIR REAR LH CHASSIS, REAR FENDER INNER PANEL & REALIGN THE SAME	1,800.00	1 LA	1,800.00	1500 ✓
33 REMOVE & REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	100.00	1 LA	100.00	✓
34 PUTTY & RESPRAY ON REAR COMAPRTMENT, REAR BOTH FENDERS, REAR PANEL, TAILLAMP PANEL, BOOT, HINGES, REAR BUMPER, SPOILER AND LOWER SKIRT	1,500.00	1 LA	1,500.00	1400 ✓
35 RUSTPROOFING	100.00	1 LA	100.00	✓
				3,600.00

Total S\$ 8,483.00

Add GST @ 7% 593.81

Total Amount payable S\$ 9,076.81

Supp: 1 pc 8637A 176 Buzzer sensor #68

1 unit rear compartment panel top coat #805N

For Cheng Hoe Motor Pte Ltd

Parts #3328
SN # 870
Supp # 68
Labour # 3200
Supp Labour # 80

#7546

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department

WS Ref: TP CHINA
Claim Type: Third Party
Accident Date: 10/05/2022
TP Veh Reg No: PC4563K

Claim No: ES2290475
Estimate No: ES2290475 /YISHUN
Date: 14 May 2022
Policy No:
Veh Reg No: SKX7680J
Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4A/T
Chassis No: JMYSRCY2A8U007002
Engine No: 4A910082765
Reg. Date: 28/08/2008

Estimate Repair Cost to Vehicle No : SKX7680J

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary 1				
Cost Plus				
1 BUZZER ESNSOR	68.00	1 PC	68.00 ✓	68.00
Labour				
2 REAR COMPARTMENT PANEL TOP COAT	80.00	1 PC	80.00 ✓	80.00

Total S\$ 148.00
GST Amount S\$ 10.36
Total Amount payable S\$ 158.36

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE