

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estlmate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

After-Paint:

Contacts :

Vehicle Nos : SMS 5987 R

Model : Toyota C-HR

Year : 2019

Chassis No : ZYX102174029

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 869.90	\$ 585 ✓ 869.90
2	Front bumper lower	1	\$ 686.20	\$ 359 ✓ 686.20
3	Front bumper inner sponge	1	\$ 358.20	\$ 358.20
4	Front bumper reinforcement	1	\$ 653.70	\$ 399 ✓ 653.70
5	Front bumper centre grille	1	\$ 337.20	\$ ✓ 337.20
6	Front bumper fog lamp garnish RH	1	\$ 210.00	\$ 121 ✓ 210.00
7	Front grille	1	\$ 487.60	\$ 487.60
8	Front grille logo	1	\$ 185.00	\$ 185.00
9	Front bumper radar sensor	1	\$ 2,781.60	\$ 2,781.60
10	Front support panel	1	\$ 978.00	\$ 978.00
11	Front support panel top garnish	1	\$ 166.30	\$ 166.30
12	Front fender RH	1	\$ 1,233.00	\$ 1,233.00
13	Front fender inner cowling RH	1	\$ 377.75	\$ 377.75
14	Front fender inner cowling bracket RH	1	\$ 68.30	\$ 68.30
15	Front fender arch garnish RH	1	\$ 371.82	\$ 195 ✓ 371.82
16	Front wheel house panel RH	1	\$ 894.30	\$ 894.30
17	Headlamp RH	1	\$ 2,898.00	\$ ✓ 2,898.00
18	Headlamp lower bracket RH	1	\$ 182.30	\$ 182.30
19	Headlamp panel RH	1	\$ 388.50	\$ 388.50
20	Wiper washer tank	1	\$ 410.60	\$ 282 ✓ 410.60
21	Wiper washer tank motor	1	\$ 228.60	\$ 228.60
22	Rear bumper	1	\$ 827.60	\$ 545 ✓ 827.60
23	Rear bumper lower	1	\$ 523.60	\$ 523.60
24	Rear bumper reflector RH	1	\$ 151.80	\$ 151.80
25	Rear bumper reflector garnish RH	1	\$ 255.00	\$ 255.00
26	Rear bumper towing cap	1	\$ 145.60	\$ 145.60
27	Rear fender RH	1	\$ 1,237.50	\$ 1,237.50
28	Rear fender wheel arch garnish RH	1	\$ 187.60	\$ ✓ 187.60
29	Rear fender inner cowling RH	1	\$ 198.90	\$ 198.90
30	Rear fender air vents RH	1	\$ 86.40	\$ 86.40
31	Rear door RH	1	\$ 1,467.50	\$ 1,467.50
32	Taillamp RH	1	\$ 658.30	\$ 658.30

BRV ✓

BRV ✓

NSX

BT ✓

BR ✓

BRV ✓

NDX

PDXR

NDX

Cut ✓

NDX

BRV ✓

NDX

BRV ✓

NDX

Cut ✓

NDX

Cut ✓

NDX

NDX

NDX

Cut ✓

NDX

NDX

NDX

33	Rear absorber RH	1	\$	454.30	\$ 392 ✓	454.30
34	Rear knuckle arm	2	\$	971.00	\$ 584 ✓	1,942.00
35	Rear Knuckle arm bearing	2	\$	431.60	\$ 344 ✓	863.20
36	Rear lower arm	2	\$	571.00	\$ 497 ✓	1,142.00
37	Rear control arm RH	1	\$	450.00	\$ ✓	450.00
38	Rear center arm RH	1	\$	458.00	\$ ✓	458.00
39	Rear ABS sensor RH	1	\$	384.00	\$ 256 ✓	384.00
40	Rear anti-roll bar	1	\$	620.40	\$ 450 ✓	620.40
41	Rear crossmember	1	\$	1,726.30	\$ 1455 ✓	1,726.30
				Parts Sub Total :	\$	28,546.87
				Discount :	\$	7,136.72
				PARTS TOTAL :	\$	21,410.15

10,794.80
-25%
8096.10

25%

BT ✓
DD ✓
JM ✓
BT ✓
BT ✓
BT ✓
CU ✓
BT ✓
BT

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ -80.00
2	Front bumper clips	1	\$ 50.00	\$ 30.00 ✓ 50.00
3	Front bumper lower clips	1	\$ 50.00	\$ 50.00
4	Front bumper side retainer	2	\$ 85 142.00	\$ 170 ✓ 284.00
5	Front bumper centre grille clips	1	\$ 50.00	\$ 20.00 ✓ 50.00
6	Front grille clips	1	\$ 50.00	\$ -50.00
7	Front support panel sealant	1	\$ 100.00	\$ -100.00
8	Front support panel top garnish clips	1	\$ 50.00	\$ 20.00 ✓ 50.00
9	Front fender sealant	1	\$ 100.00	\$ -100.00
10	Front fender inner cowling clips	1	\$ 50.00	\$ -50.00
11	Front fender arch garnish clips	1	\$ 50.00	\$ 20.00 ✓ 50.00
12	Rear bumper clips	1	\$ 50.00	\$ 30.00 ✓ 50.00
13	Rear bumper side retainer	2	\$ 85 114.40	\$ 170 ✓ 228.80
14	Rear bumper lower clips	1	\$ 50.00	\$ -50.00
15	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 ✓ 500.00
16	Rear fender sealant	1	\$ 100.00	\$ -100.00
17	Rear fender inner cowling clips	1	\$ 50.00	\$ -50.00
18	Rear alloy rim RH	2	\$ 980.00	\$ 1050 ✓ 1,960.00
19	Rear tyre RH (80% of 300)	1	\$ 480.00	\$ 240 ✓ 480.00
SPECIAL NETT TOTAL :				\$ 4,332.80

NNX
NECV
NSX
NECV
NECV
NNX
NECV
NNX
NECV
NNX
NECV
NNX
SCV
NNX
BRV
BRV

1950

Nos.	LABOUR		\$S
1	R&R front bumper radar sensor		\$ 150.00
2	Front check wiring		\$ 100.00
3	Front upholstery		\$ -200.00
4	Alignment radar sensor		\$ 150 300.00
5	Front panel beating		\$ 400.00 1,200.00
6	Front rust proofing		\$ -200.00
7	Front spray painting		\$ 2,000.00 1,000.00
8	R&R rear bumper reverse sensor		\$ 60.00 -100.00
9	R&R rear under carriage		\$ 120.00 350.00
10	R&R rear crossmember		\$ 70.00 150.00
11	R&R rear tyre and balancing		\$ 30.00 100.00
12	Wheel alignment		\$ 60.00 180.00
13	Diagnostic reset fault code		\$ -200.00
14	Rear upholstery		\$ -300.00
15	Rear check wiring		\$ -100.00
16	Rear panel beating		\$ 400.00 1,200.00
17	Rear rust proofing		\$ 200.00
18	Rear spray painting		\$ 200.00 1,200.00
LABOUR TOTAL :			\$ 7,330.00

Survey	Resurvey
12/5/2022	13/5/2022
1200 hrs	1248 hrs
TGUm	TGUm hr.
mm	
Lamp sum repair	
Repair day 8	

LABOUR TOTAL :	\$	7,330.00
----------------	----	----------

1690

PARTS TOTAL :	\$	21,410.15
SPECIAL NETT TOTAL :	\$	4,332.80
LABOUR TOTAL :	\$	7,330.00
GRAND TOTAL :	\$	33,072.95

11,736.10

L/S - 9388.88
= 9400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Registrar

Signature:

Date: