



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHIN HON (CHEN JINHONG) BLK 634 VEERASAMY ROAD #21-144 SINGAPORE 200634 Contact No Mobile: 96566324	Cust No/Name /TAN CHIN HON (CHEN JINHONG) Reg No/Reg Date SML1560B*KC17/ 08/05/201 Date In/Mileage / 0 Chassis No KNAD6811VK6295761 Engine No G3LCKP029036 Make/Model KIA/STONIC 1.0 A BET Colour/Trim BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	12/05/2022/ 10:12	TLC	442 / CocoLu	50864			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3840.00
RENEW FRT BUMPER, FRT FENDER RH, BONNET, FRT SUPPORT PANEL					640 x 6			
REPAIR FRT WHEELHOUSING RH, FRT CHASSIS RH								100.00
E PNT88000								3850.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
E PNT98000								2200
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT HOUSING					550 x 4			
FRT FENDER LH, FRT CHASSIS RH								X 500.00
E PNT88000								30.00
TO STRAIGHTEN FRT CHASSIS								
A 90000001								X 120.00
CHECK WIRING & ELECTRICAL SYSTEM								
B WHEELALIGNMENT120L								80.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								85
APPLY SEALANT FOR ACCIDENT PORTION								
S SPECIALISTJOB								85
WO:1288916 ACCIDENT TOWED FROM MIDDIE RD TO CNC PG								
Date 10/5/22( Tue) Time Start 11.27am Time End 12.45pm								
Normal Towing \$50 Add Accident \$10								
Total Cost \$60								80.00
M SUNDRY								280.00
TOP UP AIRCON GAS								
A 10028901								X 350.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
A 90000001								20.00
RENEW FRT UNDER CARRIAGE								
M SUNDRY								
Sundry								
M COVER-FR BUMPER,LWR					1.00	507.00	00.00	507.00
M COVER-FR BUMPER UPR					1.00	680.00	00.00	680.00
M GRILLE-FRONT BUMPER					1.00	132.00	00.00	132.00
M SKID PLATE-FR BUMPER					1.00	76.00	00.00	76.00

Confirm &amp; accepted by

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Page 1 of 3





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHIN HON (CHEN JINHONG) BLK 634 VEERASAMY ROAD #21-144 SINGAPORE 200634 Contact No Mobile: 96566324	Cust No/Name /TAN CHIN HON (CHEN JINHONG) Reg No/Reg Date SML1560B*KC17/ 08/05/201 Date In/Mileage / 0 Chassis No KNAD6811VK6295761 Engine No G3LCKP029036 Make/Model KIA/STONIC 1.0 A BET Colour/Trim BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	12/05/2022/ 10:12	TLC	442 / CocoLu	50864			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LIP ASSY-FRONT BUMPER	X nn				1.00	43.00	00.00	43.00
M GRILLE ASSY-RADIATOR	X nn				1.00	447.00	00.00	447.00
M COVER-RADIATOR GRILLE UPR	BR				1.00	63.00	00.00	63.00
M MOULDING-FRONT BUMPER A/INTAKE	X nn				1.00	84.00	00.00	84.00
M ABSORBER-FRONT BUMPER ENERGY	X nn				1.00	135.00	00.00	135.00
M STIFFNER-FR BPR LWR	X nn				1.00	170.00	00.00	170.00
M AIR DUCT-FR BUMPER, RH	CR4				1.00	52.00	00.00	52.00
M COVER-FR BUMPER FOG LAMP, RH	MIS				1.00	88.00	00.00	88.00
M LAMP ASSY-FRONT FOG, RH	MIS				1.00	234.00	00.00	234.00
M BRACKET-FR BUMPER SIDE, RH	MIS				1.00	18.00	00.00	18.00
M BRACKET-FR BUMPER SIDE, LH	X nn				1.00	18.00	00.00	18.00
M GUARD ASSY-FRONT WHEEL, RH	TA				1.00	56.00	00.00	56.00
M COVER ASSY-COWL TOP	X nn				1.00	166.00	00.00	166.00
M COVER ASSY-COWL TOP, RH	X nn				1.00	10.00	00.00	10.00
M BEAM COMPLETE-FR BUMPER	00				1.00	751.00	00.00	751.00
M CARRIER ASSY-FRONT END MODULE	00				1.00	556.00	00.00	556.00
M BRACKET ASSY-CARRIER MTG, RH	9 X nn				1.00	27.00	00.00	27.00
M EXTN-FR SIDE MEMBER OTR FR, RH	9 X nn				1.00	24.00	00.00	24.00
M BRACKET ASSY-FENDER & BPR MTG,	9 X nn				1.00	16.00	00.00	16.00
M REINF-FENDER APRON UPR, RH	9 X nn				1.00	62.00	00.00	62.00
M PANEL ASSY-HOOD	00				1.00	1135.00	00.00	1135.00
M HINGE ASSY-HOOD, RH	BT				1.00	43.00	00.00	43.00
M HINGE ASSY-HOOD, LH	BT				1.00	43.00	00.00	43.00
M PANEL-FENDER, RH	00				1.00	593.00	00.00	593.00
M INSULATOR-FENDER RH	9 X nn				1.00	27.00	00.00	27.00
M LATCH ASSY-HOOD	BT				1.00	101.00	00.00	101.00
M PAD-HOOD INSULATING	CR4				1.00	136.00	00.00	136.00
M GARNISH ASSY-FNDR SIDE, RH	CR4				1.00	45.00	00.00	45.00
M LAMP ASSY-HEAD, RH	BR				1.00	2324.00	00.00	2324.00
M LAMP ASSY-HEAD, LH	BR (photo)				1.00	2324.00	00.00	2324.00
M RESERVOIR & PUMP ASSY-WASHER	CR4				1.00	152.00	00.00	152.00
M HORN ASSY-LOW PITCH	X nn				1.00	64.00	00.00	64.00
M WHEEL ASSY-ALUMINIUM	X nn				1.00	659.00	00.00	659.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHIN HON (CHEN JINHONG) BLK 634 VEERASAMY ROAD #21-144 SINGAPORE 200634 Contact No Mobile: 96566324	Cust No/Name /TAN CHIN HON (CHEN JINHONG) Reg No/Reg Date SML1560B*KC17/ 08/05/201 Date In/Mileage / 0 Chassis No KNAD6811VK6295761 Engine No G3LCKP029036 Make/Model KIA/STONIC 1.0 A BET Colour/Trim BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	12/05/2022/ 10:12	TLC	442 / CocoLu	50864			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HUB ASSY-FR WHEEL	X	11		1.00	145.00	00.00	145.00
M	ARM COMPLETE-FR LWR,RH	X	11		1.00	294.00	00.00	294.00

Steve (LKK)

12/5/22, 2:00p

WIL AL

PIP

by BL H

7 dys

Estimate

Steve (LKK)

12/5/22, 2.00p

MIL AL

P/P

M BL H

7 dys

Estimate

Confirm &amp; accepted by

7% GST on      Nett      21,750.00  
21750.00      1522.50  
Total Payable      23,272.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : STEVE LKK  
Claim : TP LONPAC  
DOA : 10.05.2022  
Emailed : 21.06.2022, 9.45am  
Date survey : 12.05.2022

VEHICLE NO : SML 1560 B  
MODEL : KIA STONIC 1.0 A  
WIP : 50864

Material	:	\$	10,075.00
Labour	:	\$	7,665.00
Sub-Total	:	\$	17,740.00
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	17,740.00
GST 7%	:	\$	1,241.80
Grand Total	:	\$	18,981.80
P - Finalise By/Date : LOI / 21/06/2022			

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 7 WORKING DAYS + 2 Days ( 1 ) Weekends  
+ 0 Days ( 0 ) Public holiday  
TOTAL DAYS REPAIR TOOK = 9

☒ TP claim YM 6871 Z

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### PRO-FORMA INVOICE

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHIN HON (CHEN JINHONG)	Cust No/Name /TAN CHIN HON (CHEN JINHONG)
BLK 634 VEERASAMY ROAD	Reg No/Reg Date SML1560B*KC17/ 08/05/2019
#21-144	Date In/Mileage 17/05/2022/ 12013
SINGAPORE 200634	Chassis/Package KNAD6811VK6295761 /#
Contact No Mobile: 96566324	Engine No G3LCKP029036
17/05/2022	Make/Model KIA/STONIC 1.0 A BET
	Colour/Trim BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	21/06/2022/ 09:28	TLC	260 / AiTing	50864			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	AIR DUCT-FR BUMPER,RH				1.00	✓ 52.00	00.00	52.00
X	COVER-FR BUMPER FOG LAMP,RH				1.00	✓ 88.00	00.00	88.00
X	LAMP ASSY-FRONT FOG,RH				1.00	✓ 234.00	00.00	234.00
X	BRACKET-FR BUMPER SIDE,RH				1.00	✓ 18.00	00.00	18.00
X	GUARD ASSY-FRONT WHEEL,RH				1.00	✓ 56.00	00.00	56.00
X	BEAM COMPLETE-FR BUMPER				1.00	✓ 751.00	00.00	751.00
X	CARRIER ASSY-FRONT END MODULE				1.00	✓ 556.00	00.00	556.00
X	PANEL ASSY-HOOD				1.00	✓ 1135.00	00.00	1135.00
X	HINGE ASSY-HOOD,RH				1.00	✓ 43.00	00.00	43.00
X	HINGE ASSY-HOOD,LH				1.00	✓ 43.00	00.00	43.00
X	PANEL-FENDER,RH				1.00	✓ 593.00	00.00	593.00
X	LATCH ASSY-HOOD				1.00	✓ 101.00	00.00	101.00
X	GARNISH ASSY-FNDR SIDE,RH				1.00	✓ 45.00	00.00	45.00
X	LAMP ASSY-HEAD,RH				1.00	✓ 2324.00	00.00	2324.00
X	LAMP ASSY-HEAD,LH				1.00	✓ 2324.00	00.00	2324.00
X	RESERVOIR & PUMP ASSY-WASHER				1.00	✓ 152.00	00.00	152.00
X	GARNISH ASSY-DELTA RH				1.00	33.00	00.00	33.00
X	BUMPER-HOOD OVERSLAM				1.00	1.00	00.00	1.00
X	PAD-HOOD INSULATING				1.00	136.00	00.00	136.00
X	COOLANT (4L)				1.00	26.00	00.00	26.00
X	ORNAMENT-KIA NO.115				1.00	38.00	00.00	38.00
Z TEXT								
TP CLAIM LONPAC YM6871Z								
DOA: 10.05.22								
SURVEYOR STEVE LKK 12.05.22								
REPAIR 07 DAYS								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	10,075.00	Nett	17,740.00
Labour	7,440.00	7% GST on	1241.80
Standard Menu	0.00		
Specialist Job	165.00	Total Payable	18,981.80
Diagnostics Job	0.00		
Sundry/Others	60.00		
Total(w/o GST)	17,740.00		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHIN HON (CHEN JINHONG)	Cust No/Name /TAN CHIN HON (CHEN JINHONG)
BLK 634 VEERASAMY ROAD	Reg No/Reg Date SML1560B*KC17/ 08/05/2019
#21-144	Date In/Mileage 17/05/2022/ 12013
SINGAPORE 200634	Chassis/Package KNAD6811VK6295761 /#
Contact No Mobile: 96566324	Engine No G3LCKP029036
17/05/2022	Make/Model KIA/STONIC 1.0 A BET
	Colour/Trim BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	21/06/2022/ 09:28	TLC	260 / AiTing	50864			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 3840.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, BONNET, FRONT SUPPORT PANEL, REPAIR RH FRONT WHEELHOUSING, RH FRONT CHASSIS, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT88000								✓ 100.00
REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR								
E PNT98000								✓ 2200.00
RESPRAY ON FRONT BUMPER, BONNET, RH FRONT FENDER, RH FRONT WHEELHOUSING, AND ALL OTHER AFFECTED AREAS TO THE SAME								
A 90000001								✓ 30.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY								✓ 40.00
APPLY SEALANT ON ACCIDENT PORTIONS								
S SPECIALISTJOB								? 85.00
ACCIDENT TOWING FROM MIDDIE RD TO CNC PG								
WO:1288916								
A 10028901								✓ 280.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
M SUNDRY								✓ 20.00
SUNDRIES								
B WHEELALIGNMENT120L								? 120.00
To Conduct Computerize Full Wheel Alignment								
E PNT88000								320.00
REPAIR LH FRONT FENDER → Supp.								
E PNT98000								550.00
RESPRAY ON LH FRONT FENDER → Supp.								
S SPECIALISTJOB								✓ 80.00
VACUUM & TOP UP A/COND GAS								
X COVER-FR BUMPER,LWR					1.00	✓ 507.00	00.00	507.00
X COVER-FR BUMPER UPR					1.00	✓ 680.00	00.00	680.00
X SKID PLATE-FR BUMPER					1.00	? 76.00	00.00	76.00
X COVER-RADIATOR GRILLE UPR					1.00	✓ 63.00	00.00	63.00

This is not an official tax invoice.  
This is a computer generated document, no signature is required.




INSURANCE CO. : LONPAC

Supplementary Parts For Registration No.: SML 1560 B

<u>Materials</u>		<u>Cost (\$)</u>	
1	Garnish assy-Delta RH	33.00 ✓	CUT
2	Bumper-Hood overslam	1.00 ✓	NEC
3	Coolant (4L)	26.00 ✓	NEC
4	Ornament-Kia No.115	38.00 ✓	NEC
Total Materials		98.00	
<u>Labour</u>		<u>Cost (\$)</u>	
1	Repair LH front fender	320.00 ✓	
2	Respray LH front fender	550.00 ✓	
Total Labour		870.00	
Taxable amount		968.00	
7% GST		67.76	
<b>Grand total</b>		<b>\$ 1,035.76</b>	

Thank You.

Yours faithfully



LOI AI TING  
SENIOR OFFICER - ADMIN  
**KIA SERVICE CENTRE**  
DID : 6568 4556 / 6568 4501  
FAX : 6565 1240 / 6567 5258