

Not Authorised
11/12/2021

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5266B

AAD2205-044

10 MAY 2022

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD5266B

JTDKB3FU903079097

200303878K

TOYOTA

PRIUS

09/05/2022

SCL 99082/A16

17/01/2019

PART

LIST

1 COVER, REAR BUMPER	\$	442.60	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70	X
1 COVER, REAR BUMPER, LOWER	\$	15.40	✓
1 GUARD, REAR BUMPER, CENTER	\$	576.30	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	117.70	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$	123.70	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$	123.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	X
1 COVER, DECK TRIM, REAR	\$	126.70	X

TOTAL \$ 2,625.60

25% \$ 656.40

\$ 1,969.20

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	95.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1 END PANEL TRIM CLIP	\$	65.00	X

TOTAL \$ 1,125.00

TOTAL PARTS \$ 3,094.20

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5266B**AAD2205-**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	2200
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	4	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	4	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	4	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	2200
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$	4	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	4	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5266B**AAD2205-**

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 XTo conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.\$ *4* 380.00 X**TOTAL** \$ **8,770.00****Over All Total** \$ **11,864.20****(PART-BY-PART) Repair Days****25 DAYS***1 1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**