

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22004480/UVY3M4**Date:** 02/06/2022**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MCF22A00000100
Claimant Vehicle No :	FBT5208G	Insured Vehicle No :	SMN4015D
Date of Loss:	04/05/2022	Nature of Claim:	TP
		Claim No:	DMCF2200039H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBT5208G		
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Engine No:	H345E0031950
Reg. Date:	16/03/2022 (Man. Year: 2021)	Chassis No:	MH3SH187000001848
Colour:	Red	Odometer:	5396 km
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120-70-15	Rear Tyre Size:	140-70-14
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,284.80	4,614.30	670.50	12.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	520.00	380.00	140.00	26.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,804.80	4,994.30	810.50	13.96
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	5,804.80	3,900.00	1,904.80	32.81

INSPECTION

Date of Assignment:	12/05/2022	
Date Inspected:	13/05/2022	Inspected At:
Estimated Period of Repair:	4.0 days	

F T FASTTRACK (HQ)
25 KAKI BUKIT ROAD 4
#01-77 SYNERGY @ KB SINGAPORE 417800

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jun 2022)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT5208G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	285.00 FL	*285.00 FL
2	1		*BALANCER (RH)	Cut	90.00 FL	*60.00 FL
3	1		*BRAKE LEVER (RH)	Bent	75.00 FL	*75.00 FL
4	1		*MIRROR (RH)	CUT	90.00 FL	*90.00 FL
5	1		*VISOR	Broken	195.00 FL	*195.00 FL
6	1		*VISOR BRACKET (LH)	Bent	63.00 FL	*63.00 FL
7	1		*VISOR COVER (LH)	Missing	48.00 FL	*48.00 FL
8	1		*FRONT COVER -MB	Cut	195.00 FL	*195.00 FL
9	1		*COVER (LH)-RED	Cut	195.00 FL	*195.00 FL
10	1		*COVER (LH) CENTER-MB	Grazed	115.00 FL	*115.00 FL
11	1		*HEADLAMP	Cracked	565.00 FL	*565.00 FL
12	1		*HEADLAMP PANEL	Cracked	115.00 FL	*115.00 FL
13	1		*BATTERY COVER	Cut	90.00 FL	*90.00 FL
14	1		*FRONT FENDER-MB	Cut	190.00 FL	*190.00 FL
15	1		*COVER (RH) -MB	Cut	195.00 FL	*195.00 FL
16	1		*COVER CENTER (RH)-MB	Cut	115.00 FL	*115.00 FL
17	1		*FLOOT BOARD (RH)-MB	Cut	125.00 FL	*125.00 FL
18	1		*COVER LOWER (RH)-MB	Cut	125.00 FL	*125.00 FL
19	1		*FOOTREST (RH)	Cut	65.00 FL	*65.00 FL
20	1		*SIDE COVER	Cut	175.00 FL	*175.00 FL
21	1		*PILLION BAR	Repair	210.00 FL	*- FL
22	1		*EXHAUST COVER	Cut	105.00 FL	*105.00 FL
23	1		*TOP BOX	Cut	480.00 FL	*300.00 FL
24	1		*SLIDER EXHAUST	Repair	180.00 FL	*- FL
25	2		*FRONT FORK (RH)&(LH) @\$618.00	Bent / Twisted	1,236.00 FL	*1,236.00 FL
26	1		*UNDER BRACKET	Bent	445.00 FL	*300.00 FL
27	1		*FRONT SIGNAL LAMP	Cracked	105.00 FL	*105.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,872.00	5,127.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	587.20	512.70
Total Parts (\$\$)	5,284.80	4,614.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT FEE	New	70.00	0.00
2	LABOUR CHARGE	New	450.00	380.00
Gross Labour Cost (S\$)			520.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >