

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737896

Estimation

Date:

13/5/2022

Vehicle:

SND655Z

Make / Model:

TOYOTA ALTIS

Chassis No:

CHINA TAIPING

	Chassi	Unit	Ti	Jnit Price	Т	Amount	
No.	Description	- Oilik	+		1		856/
	Parts Replacement:	1	15	1,024.00	\$	1,024.00	
1	BOOTLID / [/l]	1	\$	359.00	\$	359.00	456
2	BOOTLID INNER TRIM - CRY			456.00	_	912.00	4 /
3	BOOTLID REFLECTOR C/W CHROME A (A/I) ?	4	\$	75.00		300.00	
4	BOOTLID STOPPER X 1/11	1	\$	398.00	_	398.00	2561
5	BOOTLID TOP LOCK / &T	and the second		Ph 68.00	-	68.00	
6	BOOTLID TOP LOCK COVER X LAFCIN		\$	312.00	_	312.00	
7	BOOTLID OUTER CHROME MOULDING X /h/	1	\$	39.00	-	39.00	2011
8	BOOTLID LOWER LOCK X (IV)	100	\$	220.00	\$	220.00	201
9	BOOTLID WEATHER STRIP / CKY	1	\$	74.00	_	74.00	68
10	BOOTLID LOGO / NC	1	\$	65.00	\$	65.00	150
11	BOOTLID EMBLEM 'ALTIS' / ///	1	\$	312.00	\$	312.00	1801
12	BOOTLID SENSOR A (Anterna) / ISK	1	\$	65.00	\$	65.00	501
13	BOOTLID EMBLEM 'COROLLA' / //(1	\$	62.00	\$	124.00	1
14	POOTUD NUMBER PLATE LAMP X NN	2	\$	612.00	\$	1,224.00	6191
1	TALLAND C/W CHROME (KH) / U(21	_	322.00	\$	644.00	327
15	TAILAMP LOWER PANEL (FH) / DD	21	\$	698.00	\$	698.00	581
16	REAR BUMPER / //	1	\$	112.00	\$	224.00	200/
17	REAR BUMPER SIDE RETAINER / BR	(2)	-	168.00	\$	326.00	1′
18	REAR BUMPER BRACKET (Ni)	2	\$	381.00	\$	762.00	200-
19	REAR BUMPER SENSOR / UX	21	\$	587.00	\$	587.00	
20	PEAR RUMPER SENSOR WIRE HARNESS X 1111	_1_	\$		\$	395.00	337.10
21	REAR RUMPER REINFORCEMENT	1	\$	395.00	_	224.00	59.30/
22	REAR BUMPER REFLECTOR (KH) / M	21	\$	112.00	\$	315.00	1
23	REAR BUMPER UNDERCOVER CENTRE / 1/1/1	1	\$	315.00		215.00	′
24	REAR BUMPER UNDERCOVER LH X ////	1	\$	215.00	\$	236.00	
25	REAR BUMPER UNDERCOVER RH X /)/)	1	\$	236.00	\$	7 7 7 7 7 7	
26	AIR VANT X NN	1	\$	65.00	\$	65.00	
27	REAR FENDER X K	2	-	1,024.00	\$	2,048.00	
28 29	BEAR FENDER COWLING X III	2	\$	358.00	\$	716.00	379/
	REAR FENDER INNER TRIM (RH) / (ky	21	\$	398.00	_	796.00	5/9/
30	REAR WINDSCREEN MOULDING X nn	1	\$	112.00	\$	112.00	and 1
31	REAR END PANEL ✓ 00	1	\$	695.00	\$	695.00	6/1/
32	END PANEL TOP GARNISH / CRY	1	\$	278.00	\$	278.00	200
-	REAR FLOOR PANEL / 00	1	\$ 1	,025.00	\$	1,025.00	937
34	REAR SPARE TYRE TOP BOARD / CRY	1	\$	357.00	\$	357.00	291.80
35	REAR EXHAUST PIPE X (II)	1	\$	951.00	\$	951.00	
36	REAR EXHAUST PIPE HEAT SHIELD X (I)()	1	\$	398.00	\$	398.00	
37	REAR EXHAUST MOUNTING X /)/	2	\$	28.00	\$	56.00	
38	REAR EXTINOST MODITIONS STATE		•		\$	17,619.00	

Less 25%	\$ 4,404.75
Total	\$ 13,214.25

7615.80 -15% **5119.35**

					_		7
	S/Nett items:				1	50.00	-
1	REAR NUMBER PLATE X NN	1	\$	50.00	\$	The state of the s	
2	BOOTLID INSULATOR CLIPS / pl	1	\$	30.00	\$	20/30.00	1
3	BOOTLID STICKER / MI	1	\$	50.00	_	31 / 50.00 40.00	
4	TAILAMP CLIPS SET X nn	1	\$	40.00	\$	150.00	1
5	REAR FENDER SEALANT X nn	1	\$	150.00	\$	50.00	1
6	REAR FENDER COWLING CLIPS SET 💢 n) 1	\$	50.00	\$	The state of the s	ł
7	REAR FENDER INNER TRIM CLIPS SET / 1/C	1	\$	50.00	\$	20/50.00 80.00	1
8	REAR WINDSCREEN SEALANT X nn	1	\$	80.00	\$	80.00	
9	REAR WINDSCREEN INNER SEAL X pr	1	\$	80.00	\$		1
10	REAR END PANEL TOP GARNISH CLIPS / N	1	\$	30.00	\$.	20/30.00 30/120.00	1
11	REAR END PANEL SEALANT / ML	1	\$	120.00	5	56 /150.00	1
12	REAR SPARE TYRE PANEL SEALANT / pl		\$	150.00		400.00	170
12	REVERSE CAMERA X Nh	1	\$	400.00	\$	3,060.00	1/
					\$	3,060.00	100
	Labour to: Rear		<u> </u>		_	1,600.00	1200
1	SPRAY PAINTING ON AFFECTED AREAS	1	4 4 5 6 6 6	1,600.00	\$	2,200.00	1400
2	PANEL BEATING ON AFFECTED AREAS	1		2,200.00	\$		1400
3	REMOVE AND REFIR REAR WINDSCREEN GLASS	1	\$	150.00			ł
4	REMOVE AND REFIR REAR BOOTLID MECHANISM	1	\$	100.00		80 100.00 80 150.00	ł
5	REMOVE AND REFIR REAR EXHAUST SYSTEM	1	\$	150.00		00	ł
6	REMOVE AND REFIR FUEL TANK ASSY	1	\$	150.00		-	ł
7	REAR CHASSIS ALIGNMENT	1	\$	200.00	\$	X 200.00	ł
8	TO CHECK ELECTRICAL WIRING	1	\$	100.00	-	50 100.00	/
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$	50.00	\$	50.00	2860
-					\$	4,700.00	1,000
15		Parts Replacement Amount			\$	16,274.25	
	Total A	Total Amount for Labour			\$	4,700.00	
						20,974.25	l
1	Total Amount \$						041-
						-	21/10

Stew (LKK) MM 1 = 8749-35 13/5/22, 10.00 L/S L/S-6999.48 M/1 y= 1000 8 L/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis:
- . No illegal modification(s) is allowed
- Supplementary item(s) must be inserveyed and is subject to final approval from inserting Company

Acknowledged by Repairer

Dalas