

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Veron.

DATE : 11.05.22

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKX5630S
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 11.05.20
TIME OF ACCIDENT : 07:20HRS

MR053REH104540349.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER Distorted	1	\$ 539.30	\$ 539.30
2	FRONT BUMPER FOG LAMP RH Cracked	1	\$ 310.90	\$ 310.90
3	FRONT BUMPER FOG LAMP COVER RH Lt	1	\$ 123.10	\$ 123.10
4	FRONT BUMPER LOWER GRILLE New	1	\$ 170.80	\$ 170.80
5	FRONT GRILLE TOP RUBBER New	1	\$ 145.60	\$ 145.60
6	FRONT BUMPER BOTTOM COVER New	1	\$ 156.50	\$ 156.50
7	FRONT BUMPER SIDE RETAINER RH Bump	2	\$ 85.10	\$ 170.20
8	FRONT BUMPER REINFORCEMENT SPONGE Cracked	1	\$ 102.20	\$ 102.20
9	FRONT BUMPER REINFORCEMENT Distorted	1	\$ 397.30	\$ 397.30
10	FRONT GRILLE LOGO New	1	\$ 48.90	\$ 48.90
11	FRONT RADIATOR GRILLE C/W CHROME Cracked	1	\$ 643.80	\$ 643.80
12	FRONT FENDER RH Buckled	1	\$ 781.20	\$ 781.20
13	FRONT FENDER EMBLEM (VVTI) RH New	1	\$ 38.90	\$ 38.90
14	FRONT FENDER INNER COWLING torn RH	2	\$ 199.20	\$ 398.40
15	FRONT FENDER SUPPORT BRACKET RH Rys	1	\$ 85.30	\$ 85.30
16	FRONT WHEEL HOUSE EXTEND PANEL RH Rys	1	\$ 295.50	\$ 295.50
17	FRONT ABS SENSOR RH New	1	\$ 543.91	\$ 543.91
18	FRONT WHEEL RIM RH Lt	1	\$ 2,010.70	\$ 2,010.70
19	FRONT CROSS MEMBER New	1	\$ 2,024.10	\$ 2,024.10
20	FRONT KNUCKLE ARM RH New	1	\$ 628.10	\$ 628.10
21	FRONT LOWER ARM RH Bent	1	\$ 732.50	\$ 732.50
22	FRONT KNUCKLE ARM BEARING RH Bump	1	\$ 128.10	\$ 128.10
23	FRONT STABILIZER BAR LINKAGE RH New	1	\$ 237.20	\$ 237.20
24	FRONT DRIVESHAFT RH New	1	\$ 1,287.50	\$ 1,287.50
25	FRONT SHOCK ABSORBER RH New	1	\$ 438.80	\$ 438.80
26	FRONT STEERING RACK AND PINION New	1	\$ 1,955.70	\$ 1,955.70
27	HEADLAMP RH Cracked	2	\$ 2,999.56	\$ 5,999.12

✓
✓
✓
✓
+
+
85.10
✓
✓
466
✓
199.20
+
+
+
580/50
+
602
✓
X
X
X
X 2816
2999.56

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKX5630S
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 11.05.20
 TIME OF ACCIDENT : 07:20HRS

28	HEAD LAMP LOWER BRACKET <i>Not nec</i>	4	\$ 62.10	\$ 248.40	+
29	BONNET <i>Not nec</i>	1	\$ 1,248.60	\$ 1,248.60	+
30	BONNET HINGE <i>2</i>	2	\$ 75.10	\$ 150.20	+
31	BONNET STOPPER <i>Not nec</i>	2	\$ 24.80	\$ 49.60	+
32	BONNET LOCK	1	\$ 135.70	\$ 135.70	+
33	BONNET LOCK BRACE PANEL <i>Not nec</i>	1	\$ 149.60	\$ 149.60	+
34	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 1,136.70	\$ 1,136.70	887
35	WASHER TANK <i>Detached</i>	1	\$ 219.10	\$ 219.10	-
36	WASHER TANK MOTOR <i>Not nec</i>	1	\$ 245.60	\$ 245.60	+
37	AIR CONDENSOR <i>2nd</i>	1	\$ 1,801.70	\$ 1,801.70	+
38	RADIATOR <i>1st</i>	1	\$ 239.70	\$ 239.70	+
39	RADIATOR TOP BRACKET <i>Not nec</i>	2	\$ 59.70	\$ 119.40	+
40	RADIATOR MOUNTING <i>Not nec</i>	4	\$ 24.50	\$ 98.00	+
41	RADIATOR TOP GARNISH <i>Not nec</i>	1	\$ 128.70	\$ 128.70	+
42	RADIATOR SPARE TANK <i>Not nec</i>	1	\$ 125.30	\$ 125.30	+

S.N: 580 784530
 5883.97

TOTAL PRICE \$ 26,489.93
 LESS 25% \$ 6,622.48
 SUB TOTAL PRICE \$ 19,867.45

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Not nec</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT BUMPER CLIPS (SET) <i>Not nec</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER BOTTOM COVER GARNISH CLIP (SET) <i>Not nec</i>	1	\$ 80.00	\$ 80.00	+
4	FRONT RADIATOR GRILLE CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00	30
5	FRONT FENDER COWLING CLIPS (SET) <i>Not nec</i>	1	\$ 80.00	\$ 80.00	30
6	FRONT FENDER UPPER CORNER GARNISH CLIP LH (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00	+
7	BONNET SEALANT <i>Not nec</i>	1	\$ 150.00	\$ 150.00	+
8	BONNET INSULATOR CLIP (SET) <i>Not nec</i>	1	\$ 80.00	\$ 80.00	+
9	FRONT SUPPORT PANEL SEALANT <i>Not nec</i>	1	\$ 100.00	\$ 100.00	+
10	RADIATOR TOP GARNISH CLIP (SET) <i>Not nec</i>	1	\$ 50.00	\$ 50.00	+
11	FRONT WHEEL TYRE LH <i>Not nec</i>	1	\$ 580.00	\$ 580.00	+
12	WHEEL CAP (SET) <i>Not nec</i>	1	\$ 120.00	\$ 120.00	+
13	BRAKE OIL <i>Not nec</i>	1	\$ 30.00	\$ 30.00	+
14	RADIATOR COOLANT <i>Not nec</i>	1	\$ 60.00	\$ 60.00	40

TOTAL \$ 1,590.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKX5630S
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 11.05.20
 TIME OF ACCIDENT : 07:20HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	700
3	WIRING CHECK	\$ 80.00	30
4	TUFF COAT	\$ 250.00	60
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	x.
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
8	REFOCUS HEADLAMP BEAM	\$ 60.00	x
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	150
10	TO PRESS FRONT WHEEL BEARING	\$ 80.00	x
11	FOUR WHEEL ALIGNMNET	\$ 120.00	80
12	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 300.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1840

TOTAL \$ 5,070.00

Adrian G
 L/S 12/05/22
 06 Days.

total: 8423.97
 L/S: 6.7K.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "without prejudice" basis
 • No illegal modifications to be carried out
 • Supplementary items from Insurance Company is subject to approval from Insurance Company

TOTAL PARTS COST : \$ 21,457.45
TOTAL LABOUR COST : \$ 5,070.00
TOTAL REPAIR COST : \$ 26,527.45

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Acknowledged by Repairer
 Signature:
 Date: