

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004492/EQY3N2**Date:** 20/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00012312100
Claimant Vehicle No :	PC3896G	Insured Vehicle No :	PC6716Z
Date of Loss:	27/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D203263/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3896G	Engine No:	ISB67E5225B22146510
Make & Model:	GOLDEN DRAGON XML6957J14, 6.7 D (A)	Chassis No:	LL3BECDH6FA011477
Reg. Date:	03/08/2015 (Man. Year: 2015)	Odometer:	189361 km
Colour:	Multi-colour		
Engine Capacity:	6690 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,406.00	8,308.00	1,098.00	11.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	3,130.00	620.00	16.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,156.00	11,438.00	1,718.00	13.06
Approved Total (Overridden) (\$\$)		9,100.00		
(\$\$)	13,156.00	9,100.00	4,056.00	30.83
+ GST 7.00/7.00% (\$\$)	920.92	637.00	283.92	30.83
Nett Amount (\$\$)	14,076.92	9,737.00	4,339.92	30.83

INSPECTION

Date of Assignment:	20/06/2022	
Date Inspected:	13/05/2022	Inspected At: Connect 3 (WOODLANDS) (HQ) 566 Woodlands Road (Mandai Estate) Singapore 728697
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jun 2022)	
Parts:	N/A	GOLDEN DRAGON XML6957J14 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3896G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH REAR VIEW MIRROR ASSY	Broken	1,550.00 F	*1,550.00 FL
2	1		*FRONT LH HEADLAMP ASSY	Cut	1,530.00 F	*1,530.00 FL
3	1		*FRONT LH ENTRANCE DOOR RUBBER	Crushed	650.00 F	*650.00 FL
4	1		*FRONT LH LINKAGE	Bent	1,050.00 F	*1,050.00 FL
5	1		*FRONT PANEL	Broken	3,200.00 F	*3,200.00 FL
6	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
7	10		*SEALANT	Necessary	400.00 FS	*400.00 FS
8	1		*ADVERTISEMENT STICKER	Necessary	1,000.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,406.00	9,106.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	798.00
Total Parts (\$\$)	9,406.00	8,308.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	New	1,000.00	900.00
2	CHECK WIRING	New	50.00	30.00
3	LABOUR CHARGES	New	1,200.00	1,000.00
4	SPRAY PAINTING WITH DESIGNS	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			3,750.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >