

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

Stew (LKK)

13/5/11, 9.31L

QT22/PC3896G/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

P-7980
 -100%
 7182
 QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC3896G

With reference to the above-mentioned, we are pleased to quote as follows:-

(nett/4) = 4256
 11,438

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front LH rear view mirror assy / BR	1	1,550.00	1,550.00 ✓
2.	Front LH headlamp assy / RT	1	1,530.00	1,530.00 ✓
3.	Front LH entrance door rubber /	1	650.00	650.00 ✓
4.	Front LH linkage / RT	1	1,050.00	1,050.00 ✓
5.	Front panel / BR	1	3,200.00	3,200.00 ✓
6.	Sealant / MC	10	40.00	400.00 ✓ nett
7.	Advertisement sticker / MC (INVAR)	1	1,000.00	1,000.00 700 nett
8.	ERP bracket / MC	1	26.00	26.00 ✓
9.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00 900
10.	Check wiring	1	50.00	50.00 80
11.	Labour charges	1	1,200.00	1,200.00 1000
12.	Spray painting with designs	1	1,500.00	1,500.00 1200
SUB-TOTAL				S\$13,156.00

- Price before 7% gst

L/S - 9150-40
 = 9100