

**TWIN WHEELS AUTO TRADING ENTERPRISE**

38 Woodlands Industrial Park E1

#03-14 Singapore 757700

Tel: 6765 2616, Fax: 6765 6177

Email: twin_woodlands@singnet.com.sg

Reference Number: PFI-2022003

Date: 18.05.2022

CUSTOMER

Name: Koufu Pte Ltd

Address: 1 Woodlands Height

Singapore 737859

VEHICLE NO.: GBD 7593 P

MODEL: VOLKSWAGEN CADDY

Quotation 3rd Party Claims - for vehicle no. GBD 7593 P with Vehicle No.SBS 3441 S

Accident on 29.04.2022, along Kallang Road

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR DOOR - LEFT <i>bt/</i>	1PC	\$ 2,009.70
2	REAR DOOR HANDLE - LEFT <i>de/</i>	1PC	\$ 285.60
3	REAR DOOR LOCK - LEFT <i>Xnn</i>	1PC	\$ 600.70
4	REAR DOOR HINGE - LEFT <i>Xnn</i>	2PCS	\$ 377.54
5	REAR TAILLAMP - LEFT <i>scn/</i>	1PC	\$ 760.50
6	REAR DOOR - RIGHT <i>bt/</i>	1PC	\$ 2,009.70
7	REAR DOOR EMBLEM <i>scn/</i>	1PC	\$ 180.97
8	REAR DOOR LOCK - RIGHT <i>Xnn</i>	1PC	\$ 600.70
9	REAR DOOR LOCK CATCH <i>Xnn</i>	1PC	\$ 200.77
10	REAR DOOR RUBBER - RIGHT <i>scn/</i>	1PC	\$ 266.90
11	REAR BUMPER <i>de/</i>	1PC	\$ 1,260.33
12	REAR BUMPER REINFORCEMENT <i>?bt/</i>	1PC	\$ 526.70
13	REAR BUMPER RETAINER <i>LH ?cn/</i>	1PC	\$ 201.94
14	REAR END PANEL <i>Xnn</i>	1PC	\$ 899.60
15	REAR END PANEL RUBBER <i>Xnn</i>	1PC	\$ 109.79
TOTAL LIST PRICE			\$ 10,291.44
LESS - 10%			\$ 1,029.14
TOTAL AMOUNT			\$ 9,262.30
PARTS - SPECIAL NETT		QTY	S/NETT
16	REAR DOOR WINDSCREEN SEALANT - LEFT <i>scn/</i>	1SET	\$ 60.00
17	REAR DOOR STICKER - 6PAX <i>scn/</i>	1PC	\$ 10.00
18	REAR DOOR STICKER - 70KM <i>scn/</i>	1PC	\$ 10.00
19	REAR DOOR WINDSCREEN SEALANT - RIGHT <i>scn/</i>	1SET	\$ 60.00
20	REAR RIGHT DOOR - COMPANY LOGO <i>scn/</i>	1SET	\$ 280.00
21	REAR BUMPER REVERSE SENSOR <i>?cut/</i>	1SET	\$ 350.00
TOTAL SPECIAL NETT PRICE			\$ 770.00

100.97
X
X
7401.37
102
6661.23

30
30
100
200?

	LABOUR CHARGES	
22	TO DISMANTLE & REFIX LEFT & RIGHT DOOR WINDSCREEN GLASS.	\$ 240.00
23	LABOUR TO SPRAY PAINT	\$ 900.00
24	LABOUR TO PANEL BEATING	\$ 950.00
	TOTAL LABOUR	\$ 2,090.00

180
400
600
1180

Subtotal \$ 12,122.30
GST 7% \$ 848.56
Grand Total \$ 12,970.86

Rasul

Hp 9001268

5 days

4/8

19/05/22 @ 1615

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 6661.23

S/N - 380.00

L - 1180.00

Supp - 331.38

T - 8552.61

20%

6842.08

415 - \$6,850