



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGG9711C

Mr Wee

C/O Allianz Insurance Singapore
Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897
Tel : +65 63953836

Vehicle & Document Information

WIP No 56761
Reg No/Reg Date SGG9711C / 29/03/2021
Date In/Mileage 31/05/2022 / 25756
Chassis No W1N2539802F9181303
Engine No 26492030366755
Make/Model MB/GLC 200
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSM00128	Cash	15/09/2022/ 19:09	CH	371 / Go Chee Han					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : SP2001168152-01 // 3-5-2022									
TOW IN/EXCESS : 5-5-2022 // NIL									
DATE IN/DATE SURVEY: 12-5-2022 // STEVE - LKK									
BY/AUTHORIZED ON : 31-5-2022 // SHIAU CHAN - LKK									
A 54700401					FRAME FLOOR WIRING HARNESS REPLACE WITH REMOVE/INSTALL EVAPORATOR UNIT INSTRUMENT PANEL & HEADLINER & STEERING COLUMN & AIRBAG & FUSE BOX DETACHABLE PARTS IN AREA TO BE REPAIRED.				12480.00
A BPILAB					DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH				960.00
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB					REMOVE, INSTALL RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS- VACUUM AND REGAS . NETT			0.07	500.00
A BPILAB					CHECK & RECTIFY ALL ELECTRONICS PARTS & WIRING TO IDENTIFICATION STANDARD.				1920.00
A BPILAB					SEAT AND FLOOR COVERING (ALL) REMOVE/INSTALL, TO REPLACE FLOOR COVERING				1920.00
A BPILAB					CLEAN VEHICLE INTERIOR FLOOR. NETT				960.00
X LEFT LINING, FRONT FLOOR						1.00	998.37	00.00	998.37
X RIGHT LINING, FRONT FLOOR						1.00	1092.74	00.00	1092.74
X LINING, REAR FLOOR						1.00	1484.53	00.00	1484.53
X MAIN ELECTRICAL WIRING HARNESS						1.00	10173.93	00.00	10173.93
X IGNITION/STARTER SWITCH CONTROL UNIT						1.00	689.25	00.00	689.25
X COCKPIT ELECTRICAL WIRING HARNESS						1.00	3230.46	00.00	3230.46
X RH/FRONT SEAT BELT						1.00	731.35	00.00	731.35

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SGG9711C

Mr Wee

C/O Allianz Insurance Singapore
Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897
Tel : +65 63953836

Vehicle & Document Information

WIP No **56761**
Reg No/Reg Date **SGG9711C / 29/03/2021**
Date In/Mileage **31/05/2022/ 25756**
Chassis No **W1N2539802F9181303**
Engine No **26492030366755**
Make/Model **MB/GLC 200**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	15/09/2022/ 19:09	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LH/FRONT SEAT BELT	1.00	731.35	00.00	731.35
X BODY-SIDE ENGINE WIRING HARNESS	1.00	3318.86	00.00	3318.86
X COVER	1.00	24.60	00.00	24.60
X CLAMP	3.00	7.45	00.00	22.35
X RADIATOR ANTIFREEZE	1.00	34.86	00.00	34.86

Confirmed & accepted by

7% GST on **Nett 41,652.65**
2915.69

Authorized signatory and company stamp

Total Payable 44,568.34

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGG9711C

Mr Wee

C/O Allianz Insurance Singapore
Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897
Tel : +65 63953836

Vehicle & Document Information

WIP No 56761
Reg No/Reg Date SGG9711C / 29/03/2021
Date In/Mileage 31/05/2022 / 25756
Chassis No W1N2539802F9181303
Engine No 26492030366755
Make/Model MB/GLC 200
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	15/09/2022/ 19:09	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : SP2001168152-01 // 3-5-2022

TOW IN/EXCESS : 5-5-2022 // NIL

DATE IN/DATE SURVEY: 12-5-2022 // STEVE - LKK

BY/AUTHORIZED ON : 31-5-2022 // SHIAU CHAN - LKK

X COCKPIT ELECTRICAL WIRING HARNESS

X RH/FRONT SEAT BELT

X LH/FRONT SEAT BELT

X BODY-SIDE ENGINE WIRING HARNESS

X COVER

X CLAMP

X RADIATOR ANTIFREEZE

Stained by water	1.00	3230.46	00.00	3230.46 ✓
Stained by water	1.00	731.35	00.00	731.35 ✓
Stained by water	1.00	731.35	00.00	731.35 ✓
Stained by water	1.00	3318.86	00.00	3318.86 ✓
BR	1.00	24.60	00.00	24.60 ✓
NEC	3.00	7.45	00.00	22.35 ✓
NEC	1.00	34.86	00.00	34.86 ✓

Confirmed & accepted by

7% GST on 8093.83
Nett 8,093.83
566.57

Authorized signatory and company stamp

Total Payable 8,660.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg