



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGG9711C

Mr Wee

C/O Allianz Insurance Singapore  
Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897  
Tel : +65 63953836

## Vehicle &amp; Document Information

WIP No 56761  
Reg No/Reg Date SGG9711C / 29/03/2021  
Date In/Mileage 31/05/2022 / 25756  
Chassis No W1N2539802F9181303  
Engine No 26492030366755  
Make/Model MB/GLC 200  
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	15/09/2022/ 19:09	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : SP2001168152-01 // 3-5-2022

TOW IN/EXCESS : 5-5-2022 // NIL

DATE IN/DATE SURVEY: 12-5-2022 // STEVE - LKK

BY/AUTHORIZED ON : 31-5-2022 // SHIAU CHAN - LKK

X COCKPIT ELECTRICAL WIRING HARNESS

X RH/FRONT SEAT BELT

X LH/FRONT SEAT BELT

X BODY-SIDE ENGINE WIRING HARNESS

X COVER

X CLAMP

X RADIATOR ANTIFREEZE

Stained by water	1.00	3230.46	00.00	3230.46	✓
Stained by water	1.00	731.35	00.00	731.35	✓
Stained by water	1.00	731.35	00.00	731.35	✓
Stained by water	1.00	3318.86	00.00	3318.86	✓
BR	1.00	24.60	00.00	24.60	✓
NEC	3.00	7.45	00.00	22.35	✓
NEC	1.00	34.86	00.00	34.86	✓

Confirmed &amp; accepted by

7% GST on 8093.83  
Nett 8,093.83  
566.57

Authorized signatory and company stamp

Total Payable 8,660.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg