

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 17 May 2022

Preliminary Advice

Insured : GBB7280C

Vehicle No

TP Vehicle : SNC8405G
No

Accident Date : 12/05/2022

Make : TESLA MODEL 3
STANDARD RANGE

Assignment Date : 12/05/2022

Date of : 13/05/2022
Inspection

Est. Duration of : 5
Repair

Inspection At : OPTIMA WERKZ PTE LTD (HQ)
10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05 AMK
AUTOPOINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,754.48
Revised Amount	:S\$	2,879.90
Check Items (Estimated)	:S\$	3,117.48
Total	:S\$	5,997.38

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.