



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004499/Kvy3n2	
			Date: 30/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 7663B	Veh. Inspected	SDL 1528C
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201647/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	12/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053AK5004010794	Colour	METALLIC BLUE
	Odometer	104500 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	MICHELIN	6 mm
	L/H Front Tyre	215/55 R17	MICHELIN	6 mm
	R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	215/55 R17	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/05/2022	Inspection Date	23/05/2022
	Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	