



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO22004500/Uvy3s2

Date: 30/05/2022

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 3239Y	Veh. Inspected	FBK 2080Z
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2201592/AGC	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	12/05/2022

2. Vehicle Particulars & Condition

Make & Model	KYMCO SK60AE	c.c	299
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	RFBV20020B2900136	Colour	BLACK
Odometer	129917 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/80-14	CITY GRIP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70-15	CITY GRIP	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND O/S BODY.
DAMAGSE SEE DETAILS.

5. General Information

Accident Date	09/05/2022	Inspection Date	13/05/2022
Survey held at	1 Kaki Bukit Ave 6 #02-32 Autobay @ Kaki Bukit		
Repairer	BISADO MOTORING		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------