

Our Ref: **SLS28D**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BUMPER		\$ XR 840.00
2	1	REAR BUMPER REFELCTOR RH		\$ cut ✓ 230.00
3	1	REAR BUMPER PARKING SENSOR OUTER RH		\$? 170.00
			SUB TOTAL	\$ 1,240.00
			MARGIN 10%	\$ 124.00
			TOTAL AMOUNT	\$ 1,364.00

Our Ref: **SLS28D**

S/NO	QTY	<u>SPECIAL NETT ITEMS</u>	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS		\$ 30 50.00
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 1,414.00

No ^{major} ~~change~~ parts allowed.

Labour only labour and spray painting. Hence
~~become~~ repair recommended to P/P