



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SLS28D (SIEW)**

Date: **11-May-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

79 Robinson Road
#09-01,
Singapore 068897

Assessed Vehicle No : **SLS28D**
Car Make and Model : **AUDI Q7 3.0 TFSI QU (333 BHP)**
Date of Accident : **8-May-22**
Date of Assessment : **11-May-22**

We have carried out a physical assessment of SLS28D at our workshop Auto Insure Pte Ltd sustained damages to the REAR RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**
Adjusted Amount : **\$ 2,486.68**
Est. Repair Days : **3**



Pursuant to your instruction, we have **AUTHORIZED** to repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SLS28D**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	1	REAR BUMPER		\$ XR 840.00
2	1	REAR BUMPER REFELCTOR RH		\$ cut ✓ 230.00
3	1	REAR BUMPER PARKING SENSOR OUTER RH		\$ nn ? 170.00
			SUB TOTAL	\$ 1,240.00
			MARGIN 10%	\$ 124.00
			TOTAL AMOUNT	\$ 1,364.00

Our Ref: **SLS28D**

S/NO	QTY	<u>SPECIAL NETT ITEMS</u>	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS		\$ 30 50.00
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 1,414.00

Our Ref: **SLS28D**

S/NO	DESCRIPTION	EST. BY WORKSHOP	
	<u>LABOUR & PAINTWORK</u>		
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS	\$ 250	400.00
2	TO REMOVE & REFIT REAR BUMPER PARKING SENSORS	\$ 30	50.00
3	SIMPLE WIRING	\$ ✓	20.00
4	ANTI RUST COATING	\$ xnn	20.00
5	PAINT MATERIALS PER PANEL	\$ 250	400.00
6	SUNDRIES	\$ xnn	20.00
TOTAL BEFORE GST		\$	2,324.00
LESS EXCESS		\$	-
TOTAL BEFORE GST		\$	2,324.00
7% GST		\$	162.68
TOTAL REPAIR COST		\$	2,486.68

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*****On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.**

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 97495749

Not Authorise

Excess; to be advise

13/5/22

2 days

Resurvey new parts

taufikh@lkkauto.com