

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0367/2022/JT
DATE : 11-May-22
WIP : 23327

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Guo Qiang,

5 days - ok - Jy - 29 Jul 22

OWNER'S NAME : MS FOO ANQI SHARON
ADDRESS : 19 TOH TUCK ROAD
#01-44
SINGAPORE 596683
TELEPHONE : HP +65 96901155
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210049960-01
VEHICLE NO : **SMZ 9693 A**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 27/05/2021
ENGINE NO : DFY 272235
CHASSIS NO : WAUZZZGY3MA100989
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 07-May-22
PLACE OF ACCIDENT : KK HOSPITAL CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 9693 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	\$ 350.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS SILL PANEL AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 750.00
3	TO RESPRAY LHS REAR DOOR, LHS SILL PANEL AND LHS REAR FENDER.	\$	3,000.00	\$ 1,650.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,922.00	\$ 2,942.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 9693 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH	1	\$ 2,466.00	\$ 1,972.80
2	REAR DOOR OUTER SEAL - LH	1	\$ 179.00	\$ 142.80
3	REAR DOOR CATCH	1	\$ 93.00	
4	REAR WHEEL SPOILER - LH	1	\$ 32.00	
5	REAR WHEEL HOUSING LINER - LH	1	\$ 260.00	
6	REAR ALUMINIUM RIM	1	\$ 1,435.00	
7	RUBBER VALVE	1	\$ 4.00	
8	STONE CHIP	S/N	\$ 180.00	\$ 180.00
9	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 4,999.00	\$ 2,295.60
TOTAL LABOUR CHARGES		:	\$ 5,922.00	\$ 2,942.00
GRAND TOTAL		:	\$ 10,921.00	\$ 5,237.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-30/06/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT