


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0368/2022/JT
DATE : 11-May-22
WIP : 23181

VEHICLE IN WORKSHOP. SURVEY TBC

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#19-00 THE OCTAGON
SINGAPORE 069534
Attn: Ms Angie - Motor Claims Dept/ Windscreen
Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR PHANG YU KANG
ADDRESS : 259 WESTWOOD AVENUE
SINGAPORE 648459
TELEPHONE : HP +65 98394884
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPCSNW00109982200
VEHICLE NO : SNE 6843 C
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 24/7/2019
ENGINE NO : CHZ B23499
CHASSIS NO : WAUZZZ8V9KA090969
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-May-22
PLACE OF ACCIDENT : TUAS TOWARDS CITY BEFORE CLEMENTI AVENUE 6

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNE 6843 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00 /	
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	? nn
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 /	
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 /	
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIRBAGS AND KNIFE AIRBAG.	S/N \$ 3,600.00 /	
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS.	S/N \$ 2,800.00	? nn
SUB TOTAL LABOUR CHARGES		: \$ 9,240.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNE 6843 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	2,400.00	X nn
8	TO PLACE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	? nn
9	TO REMOVE AND RENEW ENGINE COMPONENTS.	S/N \$	980.00	? nn
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	/
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	/
12	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	/
SUB TOTAL LABOUR CHARGES		:	\$ 6,860.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNE 6843 C


S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. CUT OUT AND REWELD BOTH FENDER SUPPORT AND CLOSING ELEMENT. TO CUT OUT AND WELD BOTH FRONT TOP WHEEL HOUSING. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	3 \$ 14,000.00 12 x 700	8400
14	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR, BOTH FRONT FENDER TOP SUPPORT AND BOTH FRONT TOP WHEEL HOUSING. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	5 \$ 7,000.00 6 x 700 + 120 + 100	70 700 4460
15	TO GET AND APPROVAL FROM LTA FOR FRONT CHASSIS RENEWAL.	S/N TBC	X nn
16	TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 480.00	/ (pb75)
17	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 37,964.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / BR	1	\$	2,146.00	
2	FRONT BUMPER FIXING PARTS X nn	1	\$	195.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH X nn	2	\$	86.00	
4	FRONT BUMPER GRILLE - CENTER X ? nn	1	\$	179.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ? nn	1	\$	332.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ? nn	2	\$	636.00	
7	RADIATOR GRILLE / BR	1	\$	1,578.00	
8	RADIATOR GRILLE CLOSING ELEMENT / BR	1	\$	210.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ? nn	2	\$	420.00	
10	AIR COND STICKER / AC	1	\$	9.00	
11	CAUTION STICKER / AC	1	\$	16.00	
12	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$	211.00	
13	FRONT BUMPER REINFORCEMENT BEAM / BR	1	\$	847.00	
14	FRONT BUMPER REINFORCEMENT BEAM COVER / BR	1	\$	136.00	
15	HORN - LH / RH ? nn	2	\$	426.00	
16	FRONT FENDER - LH / RH / ON	(2)	\$	1,908.00	
17	FRONT FENDER ATTACHMENT PARTS X nn	1	\$	75.00	
18	FRONT FENDER BRACKET - LH / RH / AC	(2)	\$	112.00	
19	FRONT FENDER POP RIVET / AC	16	\$	61.00	
20	FRONT FENDER BRACKET END - LH / RH ? nn	2	\$	62.00	
SUB TOTAL SPARE PARTS		:	\$	9,645.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER CLOSING ELEMENT - LH / RH ?nn	2	\$	136.00
22	FRONT FENDER BRACE - LH / RH ?nn	2	\$	214.00
23	FRONT WHEEL HOUSING LINER - LH / RH Ynn	2	\$	366.00
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS Ynn	1	\$	60.00
25	BONNET / ON	1	\$	3,370.00
26	BONNET ATTACHMENT PARTS / NK	1	\$	172.00
27	BONNET HINGE - LH / RH / BT	2	\$	136.00
28	BONNET SIDE PANEL SEAL - LH / RH - CY	2	\$	92.00
29	BONNET EDGE PROTECTION - MI	1	\$	31.00
30	BONNET ABSORBER / BT	1	\$	110.00
31	BONNET CATCH HOOK - LOWER / BT	1	\$	100.00
32	BONNET STRIKER - LH / RH / BT	2	\$	246.00
33	WATER BOX SEAL / CNT	1	\$	66.00
34	WATER BOX SEAL ADAPTER - LH / RH / NK	2	\$	30.00
35	BONNET LOCK MICRO-SWITCH - LH / RH / BT	2	\$	455.00
36	BONNET RELEASE CABLE COVER / TN	2	\$	8.00
37	BONNET BOWDEN CABLE - INNER / TN	1	\$	64.00
38	BONNET HOOD CABLE COVER / BR	1	\$	11.00
39	BONNET LOCK CABLE / TN	1	\$	82.00
40	BONNET SOUND ABSORBER / BR	1	\$	244.00
SUB TOTAL SPARE PARTS		:	\$	5,993.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET PLENUM CHAMBER <i>BR</i>	1	\$	199.00
42	BONNET CATCH HOOK - UPPER <i>BT</i>	1	\$	71.00
43	HEADLIGHT - LH / RH <i>BR</i>	②	\$	11,758.00
44	HEADLIGHT POWER MODULE - LH / RH <i>? nn</i>	2	\$	1,700.00
45	HEADLIGHT CONTROL UNIT <i>? nn</i>	2	\$	1,249.00
46	LED HEAT SINK - LH / RH <i>? nn</i>	2	\$	1,636.00
47	HEADLIGHT HOSE - LH / RH <i>? nn</i>	2	\$	92.00
48	LIFT CYLINDER - LH / RH <i>? nn</i>	2	\$	312.00
49	LIFT CYLINDER HOSE - LH / RH <i>? nn</i>	1	\$	78.00
50	LIFT CYLINDER PUMP <i>? nn</i>	1	\$	171.00
51	FRONT WINDSCREEN WASHER SYSTEM PUMP <i>? nn</i>	1	\$	137.00
52	WASH WATER RESERVOIR <i>BR</i>	1	\$	225.00
53	WATER RESERVOIR STRAINER <i>BR</i>	1	\$	24.00
54	WATER RESERVOIR END CAP <i>BR</i>	1	\$	24.00
55	LOCK CARRIER <i>BR</i>	1	\$	806.00
56	A/C CONDENSER <i>nn</i>	1	\$	569.00
57	REFRIGERANT LINE <i>? nn</i>	1	\$	621.00
58	REFRIGERANT LINE <i>? nn</i>	1	\$	499.00
59	REFRIGERANT LINE <i>? nn</i>	1	\$	569.00
60	A/C COOLANT PIPE INNER HEAT EXCHANGER <i>? nn</i>	1	\$	604.00
SUB TOTAL SPARE PARTS			\$	21,344.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	OUTSIDE TEMPERATURE SENSOR BRACKET / <i>MA</i>	1	\$	21.00
62	ADDITIONAL RADIATOR / <i>OD</i>	1	\$	959.00
63	RADIATOR / <i>OD</i>	1	\$	1,061.00
64	RADIATOR AIR GUIDE - UPPER / <i>MIS</i>	2	\$	90.00
65	RADIATOR BUSH - LOWER / <i>NA</i>	2	\$	22.00
66	RADIATOR SEAL BIG - LOWER / <i>NC</i>	1	\$	15.00
67	RADIATOR SEAL SMALL - LOWER / <i>NC</i>	1	\$	6.00
68	RADIATOR COOLANT / <i>NC</i>	6	\$	282.00
69	RADIATOR FAN RING / <i>BR</i>	1	\$	1,488.00
70	RADIATOR AIR GUIDE - LH / RH / <i>?nn</i>	2	\$	56.00
71	RADIATOR SEAL - RH OUTER / <i>BR</i>	1	\$	9.00
72	RADIATOR AIR GUIDE - UPPER CENTER / <i>BR</i>	1	\$	14.00
73	RADIATOR COOLANT HOSE RELEASE COUPLING - FRONT / <i>?nn</i>	1	\$	251.00
74	RADIATOR COOLANT PIPE - UPPER / <i>?nn</i>	1	\$	65.00
75	RADIATOR COOLANT PIPE - LOWER / <i>?nn</i>	1	\$	34.00
76	RADIATOR COOLANT HOSE - UPPER / <i>?nn</i>	1	\$	125.00
77	RADIATOR COOLANT HOSE - LOWER / <i>?nn</i>	1	\$	60.00
78	INTAKE AIR DUCT COVER / <i>BR</i>	1	\$	30.00
79	INTAKE AIR DUCT / <i>BR</i>	1	\$	59.00
80	INTAKE AIR DUCT AIR GUIDE / <i>BR</i>	1	\$	21.00
SUB TOTAL SPARE PARTS		:	\$ 4,668.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	WATER DRAINAGE HOSE <i>MIS</i>	1	\$	37.00
82	RADIATOR AIR GUIDE HOSE <i>CNT</i>	1	\$	69.00
83	INTAKE MANIFOLD <i>BR (AV fit)</i>	1	\$	156.00
84	AIR FILTER BOX COVER <i>BR</i>	1	\$	310.00
85	INTAKE MANIFOLD <i>BR</i>	1	\$	786.00
86	CHARGE AIR COOLER <i>BR</i>	1	\$	864.00
87	THROTTLE VALVE CONTROL ELEMENT <i>? nn</i>	1	\$	796.00
88	RETAINING BAR <i>? nn</i>	1	\$	17.00
89	RETAINING BAR CLOSING ELEMENT - LH / RH <i>? nn</i>	2	\$	164.00
90	FRONT WHEEL HOUSING - LH / RH <i>2 - 00</i>	2	\$	3,086.00
91	A-PILLAR INNER - LH / RH <i>00</i>	2	\$	1,430.00
92	FUSE BOX COVER <i>BR</i>	1	\$	54.00
93	FUSE BOX <i>? nn</i>	1	\$	93.00
94	FUSE BOX CLOSING ELEMENT <i>? nn</i>	1	\$	27.00
95	FUSE HOLDER <i>? nn</i>	1	\$	24.00
96	E BOX <i>? nn</i>	1	\$	394.00
97	SIDE MEMBER CABLE GUIDE - LH <i>? nn</i>	1	\$	27.00
98	FRONT WINDSCREEN <i>BR</i>	1	\$	1,206.00
99	RAIN SENSOR GEL FOIL <i>nc</i>	1	\$	130.00
100	SPRING CLIP <i>X nn</i>	1	\$	23.00
SUB TOTAL SPARE PARTS			\$	9,693.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	PRIMER / <i>MC</i>	1	\$ 22.00	
102	FRONT WINDSCREEN WATER DEFLECTOR STRIP - LH / RH <i>21</i> / <i>167</i>	21	\$ 150.00	
103	FRONT WINDOW WIPER MOUNTING ? <i>nn</i>	1	\$ 1,284.00	
104	AERO WIPER ARM - LH / RH <i>BT</i>	2	\$ 230.00	
105	AERODYNAMIC WIPER BLADES <i>167</i>	1	\$ 101.00	
106	AERO WIPER CAP <i>X</i> <i>nn</i>	2	\$ 20.00	
107	AERO WIPER ATTACHMENT PARTS <i>X</i> <i>nn</i>	1	\$ 133.00	
108	STEERING WHEEL AIRBAG <i>OK</i>	1	\$ 3,800.00	
109	AIRBAG UNIT / <i>MC</i>	1	\$ 4,621.00	
110	HEAD AIRBAG UNIT - LH / RH <i>OK</i>	2	\$ 4,138.00	
111	KNEE AIRBAG UNIT <i>OK</i>	1	\$ 2,069.00	
112	AIRBAG CONTROL UNIT <i>MC</i>	1	\$ 1,918.00	
113	AIRBAG CRASH SENSOR <i>MC</i>	3	TBC	
114	BATTERY <i>OK</i> <i>nn</i>	1	\$ 584.00	
115	BATTERY CONTROL UNIT	1	\$ 568.00	
116	BATTERY COVER CAP ? <i>nn</i>	1	\$ 8.00	
117	BATTERY PROTECTION COVER <i>OK</i> <i>Tn</i>	1	\$ 145.00	
118	BATTERY CONSOLE <i>OK</i>	1	\$ 203.00	
119	BATTERY HEAT INSULATION <i>2</i> <i>nn</i>	1	\$ 96.00	
120	STEERING WHEEL <i>X</i> <i>nn</i>	1	\$ 2,641.00	
SUB TOTAL SPARE PARTS		:	\$ 22,731.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	DASHBOARD AIR DUCT <i>BR</i>	1	\$	5,035.00	
122	AIR VENT - CENTER <i>? nn</i>	1	\$	167.00	
123	LOUDSPEAKER COVER <i>? nn</i>	1	\$	105.00	
124	MOULDED HEADLINER <i>? CRH</i>	1	\$	2,471.00	
125	GRAB HANDLE FRONT - LH / RH <i>? nn</i>	2		TBC	
126	GRAB HANDLE REAR - LH / RH <i>? nn</i>	2		TBC	
127	A-PILLAR TRIM UPPER-LH / RH <i>? nn</i>	2	\$	364.00	
128	B-PILLAR TRIM UPPER - LH / RH <i>? nn</i>	2	\$	480.00	
129	C-PILLAR TRIM UPPER - LH / RH <i>? nn</i>	2	\$	244.00	
130	D-PILLAR TRIM UPPER - LH / RH <i>? nn</i>	2	\$	354.00	
131	SEAT BELT TENSIONER - LH / RH <i>? nn</i>	2	\$	2,454.00	
132	SEAT BELT HEIGHT ADJUSTER <i>? nn</i>	2	\$	429.00	
133	ENVIRONMENT CAMERA <i>? nn</i>	1		TBC	
134	CAMERA WIRE SET <i>? nn</i>	1		TBC	
135	FRONT SUBFRAME <i>? nn</i>	1	\$	1,105.00	
136	BONDED RUBBER BUSHES <i>? nn</i>	1	\$	116.00	
137	ENGINE MOUNTING <i>? nn</i>	1		TBC	
138	GEARBOX MOUNTING <i>? nn</i>	1	\$	286.00	
139	TRACK CONTROL ARM - LH / RH <i>? X nn</i>	2	\$	786.00	
140	STABILIZER <i>? X nn</i>	1	\$	451.00	
SUB TOTAL SPARE PARTS			\$	14,847.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 6843 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
141	FRONT WHEEL BEARING HOUSING - LH / RH X nn	2	\$	1,254.00
142	FRONT WHEELHUB BEARING X nn	2	\$	1,105.00
143	SUSPENSION GUIDE JOINT - LH / RH V nn	2	\$	274.00
144	COUPLING ROD X nn	2	\$	209.00
145	GAS SHOCK ABSORBER V nn	2	\$	562.00
146	INSULATOR SUPPORT ELEMENT X nn	2	\$	46.00
147	SHOCK ABSORBER RUBBER STOP X nn	2	\$	118.00
148	DEEP GROOVE BALL THRUST BEARING X nn	2	\$	100.00
149	SUSPENSION STRUT STORAGE X nn	2	\$	272.00
150	SUSPENSION STRUT CAP X nn	2	\$	14.00
151	TRACK ROD X nn	2	\$	196.00
152	TIE ROD END - LH / RH X nn	2	\$	252.00
153	FRONT NO PLATE / ne	S/N	\$	60.00
154	ARYLIC SEALANT / ne	S/N	\$	180.00
155	CAVITY WAX / ne	S/N	\$	140.00
156	STONE CHIP / ne	S/N	\$	180.00
157	METAL FILLER POWDER / ne	S/N	\$	280.00
158	FRONT WINDSCREEN SEALANT / ne	S/N	\$	200.00
159	SUNDRIES ? nn		\$	1,000.00
TOTAL SPARE PARTS		:	\$	95,363.00
TOTAL LABOUR CHARGES		:	\$	37,964.00
GRAND TOTAL		:	\$	133,327.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
 SURVEYED DATE :
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS :

Steve (LKK)
 13/5/22, 12.30m

0D-L1 AL
 EXP - ?
 PIP
 30 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT