



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE CIVIL DEFENCE FORCE (MHA05)		Ref:	CS3/SCD22004508/Etc
91 UBI AVE 4		Date:	13/05/2022
SINGAPORE 408827			
SINGAPORE 408827		Code:	SCD
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YN 4077H	Veh. Inspected	YP 8711Z
Policy No.		Coverage (\$)	0.00
Claim No.	SCDF REF 2022 - 48	Excess (\$)	0.00
Assign From	RALF TAY	Assign Date	12/05/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/05/2022	Inspection Date	13/05/2022
Survey held at	ASTUTE AUTOWORKS PTE LTD 60 JALAN LAM HUAT, #02-16/17, CARROS CENTRE SINGAPORE 737869		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			