

Auto Insure Pte. Ltd.

6 Marsiling Lane Singapore (739145)

E: claims01@autoinsure.com.sg W: www.autoinsure.com.sg

T: 3157 2626 F: 6368 0081 **GST No.: 201437380M**

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: GBL212T (SIEW)

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

11-May-22

79 Robinson Road #09-01.

Date:

Singapore 068897

Assessed Vehicle No : GBL212T

Car Make and Model : VOLKSWAGEN CADDY MAXI TDI DSG

Date of Accident : 30-Apr-22
Date of Assessment : 11-May-22

We have carried out a physical assessment of GBL212T at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P

Adjusted Amount : \$ 22,186.99

Est. Repair Days : 10

Pursuant to your instruction, we have **AUTHORIZED to** repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **GBL212T**

Our Ret:	GBLZIZI	DECORIDETIONS	ASSESSED	EST DV WODVSHOD
S/NO	QTY	DESCRIPTIONS	CONDITION	EST. BY WORKSHOP
		PARTS REPLACEMENT - LIST ITEMS		
1	1	BONNET		\$ 1,320.00
2	1	BONNET HINGE RH		\$ 90.00
3	1	BONNET HINGE LH		\$ 90.00
4	1	BONNET LOCK UPPER		\$ 66.00
5	1	BONNET LOCK LOWER		\$ 120.00
6	1	HEADLAMP RH		\$ 360.00
7	1	HEADLAMP LH		\$ 360.00
8	1	HEADLAMP INNER COVER RH		\$ 22.00
9	1	HEADLAMP INNER COVER LH		\$ 22.00
10	1	FRONT GRILLE CHROME RH		\$ 24.00
11	1	FRONT GRILLE CHROME LH		\$ 24.00
12	1	FRONT BUMPER		\$ 780.00
13	1	FRONT BUMPER LOGO (VW)		\$ 60.00
14	1	FRONT BUMPER TOWING COVER RH		\$ 12.00
15	1	FRONT BUMPER FOG LAMP COVER RH		\$ 90.00
16	1	FRONT BUMPER FOG LAMP COVER LH		\$ 90.00
17	1	FRONT BUMPER SIDE RETAINER RH		\$ 55.00
18	1	FRONT BUMPER SIDE RETAINER LH		\$ 55.00
19	1	FRONT BUMPER INNER BRACKET RH		\$ 145.00
20	1	FRONT BUMPER INNER BRACKET LH		\$ 145.00
21	1	FRONT TEMPERATURE SENSOR OUTER		\$ 35.00
22	1	FRONT BUMPER SPONGE UPPER		\$ 60.00
23	1	FRONT BUMPER REINFORCEMENT		\$ 385.00
24	1	FRONT BUMPER SPONGE LOWER		\$ 42.00
25	1	FRONT BUMPER REINFORCEMENT LOWER		\$ 145.00
26	1	FRONT ENGINE LOWER COVER		\$ 180.00
27	1	FRONT SUPPORT PANEL		\$ 840.00
28	1	FRONT BRACE PANEL		\$ 90.00
29	1	HEADLAMP PANEL UPPER RH		\$ 30.00
30	1	HEADLAMP PANEL UPPER LH		\$ 30.00
31	1	HEADLAMP LOWER BRACKET RH		\$ 145.00
32	1	HEADLAMP LOWER BRACKET LH		\$ 145.00
33	1	FRONT AIR GUIDE		CHECK PRICES
34	1	FRONT AIR INLET DUCT		\$ 48.00
35	1	FRONT AIR INLET COVER		\$ 24.00
36	1	AIR FILTER ASSY		\$ 345.00
37	1	AIR FILTER ELEMENT		\$ 35.00
38	1	AIR FILTER INTAKE HOSE		\$ 84.00
39	1	WIPER TANK		\$ 108.00
40	1	WIPER TANK MOTOR		\$ 90.00
41	1	AIR CON CONDENSER SIDE COVER RH		\$ 24.00
42	1	AIR CON CONDENSER SIDE COVER LH		\$ 24.00
43	1	AIR CON CONDENSER		\$ 360.00
44	1	AIR CON DISCHARGE HOSE		\$ 600.00
45	1	AIR CON SUCTION HOSE		\$ 600.00

46	1	AIR CON HOSE INNER	1	\$	600.00
47	1	AUXILIARY WATER PUMP HOSE		\$	22.00
48	1	AUXILIARY RADIATOR		\$	390.00
49	1	RADIATOR UPPER AIR DUCT		\$	66.00
50	1	RADIATOR LOWER AIR DUCT		, \$	66.00
51	1	RADIATOR UPPER BRACKET RH		, \$	36.00
52	1	RADIATOR UPPER BRACKET LH		\$	36.00
53	1	RADIATOR LOWER STOPPER RH		\$	12.00
54	1	RADIATOR LOWER STOPPER LH		\$	12.00
55	1	RADIATOR LIBER LIGGE (CMALL)		\$	390.00
56	1	RADIATOR UPPER HOSE (SMALL)		\$	22.00
57	1	RADIATOR SAN COVER		\$	96.00
58	1	RADIATOR FAN COVER		\$	180.00
59	1	RADIATOR FAN RH		\$	345.00
60	1	RADIATOR FAN LH		\$	480.00
61	1	COOLING WATER PIPE			CHECK PRICES
62	1	CHARGER INTAKE HOSE		<u>,</u>	CHECK PRICES
63	1	ENGINE WIRE HARNESS		\$	700.00
64	1	FUEL FILTER		\$	440.00
65	1	ADBLUE TANK FILLER NECK		\$	225.00
66	1	ADBLUE TANK		\$	1,440.00
67	1	ENGINE MOUNTING BLACKET RH		\$ \$	120.00
68	1	ENGINE MOUNTING RH		Þ	240.00
69	1	FRONT CHASSIS RH FRONT CHASSIS LH			REPAIR REPAIR
70 71	1	FRONT WHEEL HOUSE RH			REPAIR
72	1 1	FRONT FENDER RH		Ļ	420.00
73	1	FRONT FENDER SIGNAL LAMP RH		\$ \$	24.00
74	1	FRONT FENDER INNER SHIELD RH		\$	60.00
75	1	FRONT FENDER LH		\$	420.00
76 76	1	FRONT FENDER SIGNAL LAMP LH		\$	24.00
77	1	FRONT FENDER INNER SHIELD LH		\$	60.00
78	1	FRONT QUARTER GLASS RH		\$	90.00
78 79	1	FRONT QUARTER GLASS LH		\$	90.00
80	1	FRONT DOOR RH		Y	REPAINT
81	1	FRONT DOOR LH		REPAINT	
			SUB TOTAL	\$	15,505.00
			MARGIN 10%	\$	1,550.50
			TOTAL AMOUNT	\$	17,055.50

Our Ref: GBL212T

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP	
1	1	FRONT NUMBER PLATE & HOLDER		\$ 50.00	
2	1	FRONT BUMPER CLIPS		\$ 50.00	
3	2	FRONT FENDER INNER SHIELD CLIPS RH & LH		\$ 50.00	
4	1	AIR CON GAS		\$ 80.00	
5	1	RADIATOR COOLANT		\$ 60.00	
6	1	ADBLUE		\$ 50.00	
			SUB TOTAL	\$ 340.00	
			TOTAL PARTS COST	\$ 17,395.50	

Our Ref: GBL212T

S/NO	DESCRIPTION			EST. BY WORKSHOP	
	LABOUR & PAINTWORK				
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS			1,200.00	
2	TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING RECHARGING GAS			150.00	
3	SIMPLE WIRING			20.00	
4	TO REMOVE & REFIT ENGINE TO FACILITATE REPAIR & REPLACED ENGINE MOUNTING RH			350.00	
5	TO REPAIR & WELD FRONT CHASSIS RH & LH		\$	300.00	
6	ANTI RUST COATING		\$	60.00	
7	PAINT MATERIALS PER PANEL		\$	1,200.00	
8	SUNDRIES		\$	60.00	
		TOTAL BEFORE GST	\$	20,735.50	
		LESS EXCESS	\$	-	
		TOTAL BEFORE GST	\$	20,735.50	
		7% GST	\$	1,451.49	
		TOTAL REPAIR COST	\$	22,186.99	

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Yours Faithfully,

Jason Heng Claims Director

^{**}This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

^{***}On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.