

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
SINGAPORE 048623

TEL: 64616555 FAX: 62213147  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 11/05/2022  
TP Veh Reg No: SJZ8114Y

**Estimate No: EST2200152**

Date: 13 May 2022

Veh Reg No: **SNE3675R**

Make/Model: HONDA FIT 1.3 HOME  
CVT

Chasis No: GR11105709

Reg. Date: 08/03/2022

Your Ref No: SJZ8114Y

## Estimate Repair Cost to Vehicle No :SNE3675R

| Quantity           | Description                             | List Price | Amount     |
|--------------------|-----------------------------------------|------------|------------|
|                    |                                         | <u>S\$</u> | <u>S\$</u> |
| <b>List Price</b>  |                                         |            |            |
| 1                  | 1 PC BOOT LID                           | 1,035.60   |            |
| 2                  | 1 PC BOOTLID LOGO                       | 40.70      |            |
| 3                  | 1 PC BOOTLID "FIT" EMBLEM               | 30.80      |            |
| 4                  | 1 PC BOOT LID LOCK                      | 193.80     |            |
| 5                  | 1 PC BOOT LID LOCK CHECKER              | 58.40      |            |
| 6                  | 1 PC BOOT LID RUBBER                    | 177.40     |            |
| 7                  | 1 PC REAR WINDSCREEN RUBBER             | 97.70      |            |
| 8                  | 1 PC REAR PANEL                         | 495.10     |            |
| 9                  | 1 PC REAR PANEL TRIM                    | 91.50      |            |
| 10                 | 1 PC REAR BUMPER                        | 788.30     |            |
| 11                 | 2 PCS REAR BUMPER SIDE RETAINER         | 57.40      |            |
| 12                 | 1 PC REAR BUMPER REFLECTOR - RH         | 99.30      |            |
|                    |                                         | 3,166.00   |            |
|                    |                                         | Less 20%   | 633.20     |
|                    |                                         |            | 2,532.80   |
| <b>Special Net</b> |                                         |            |            |
| 13                 | 1 PC REAR WINDSCREEN SEAL               | 60.00      |            |
| 14                 | 1 PC REAR WINDSCREEN SEALANT            | 60.00      |            |
| 15                 | 1 SET REAR PANEL TRIM CLIPS             | 40.00      |            |
| 16                 | 1 SET REAR BUMPER CLIPS                 | 40.00      |            |
| 17                 | 1 SET REVERSE SENSORS                   | 350.00     |            |
|                    |                                         | 550.00     | 550.00     |
| <b>Labour</b>      |                                         |            |            |
| 18                 | 1 TO CHECK WIRING                       | 50.00      |            |
| 19                 | 1 TO REMOVE AND REFIT REAR WINDSCREEN   | 120.00     |            |
| 20                 | 1 TO REMOVE AND REFIT THIRD BRAKE LIGHT | 80.00      |            |
| 21                 | 1 TO REMOVE AND REFIT REAR VIDEO CAMERA | 80.00      |            |
| 22                 | 1 TO REMOVE AND REFIT REVERSE SENSOR    | 80.00      |            |
| 23                 | 1 TO REMOVE AND REFIT REVERSE CAMERA    | 80.00      |            |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
SINGAPORE 048623

TEL: 64616555 FAX: 62213147  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 11/05/2022  
TP Veh Reg No: SJZ8114Y

**Estimate No: EST2200152**

Date: 13 May 2022

Veh Reg No: **SNE3675R**

Make/Model: HONDA FIT 1.3 HOME  
CVT

Chasis No: GR11105709

Reg. Date: 08/03/2022

Your Ref No: SJZ8114Y

## Estimate Repair Cost to Vehicle No :SNE3675R

| Quantity | Description                                                                                                         | List Price           | Amount              |
|----------|---------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|
|          |                                                                                                                     | <u>S\$</u>           | <u>S\$</u>          |
| 24       | 1 TO SPRAY PANEL SEALANT                                                                                            | 100.00               |                     |
| 25       | 1 TO REMOVE AND REFIT INNER TRIM                                                                                    | 100.00               |                     |
| 26       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS,<br>KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR<br>CUTTING/WELDING WORKS. | 1,000.00             |                     |
| 27       | 1 (REAR) TO SPRAY PAINTING                                                                                          | 1,000.00             |                     |
|          |                                                                                                                     | 2,690.00             | 2,690.00            |
|          |                                                                                                                     | Total                | S\$ 5,772.80        |
|          |                                                                                                                     | Add GST @ 7%         | 404.10              |
|          |                                                                                                                     | Total Amount Payable | <u>S\$ 6,176.90</u> |

TOTAL: SINGAPORE DOLLAR SIX THOUSAND ONE HUNDRED SEVENTY SIX AND CENTS  
NINETY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time  
which may be required after work has begun.

**For Kang Car Repairers Pte Ltd**



AUTHORISED SIGNATURE