



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004516/Aqcq2	
			Date: 17/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJZ 8114Y	Veh. Inspected	SNE 3675R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201643/RE	Excess (\$)	0.00
	Assign From	IRENE HENRY	Assign Date	13/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	GR11105709	Colour	BLUE
	Odometer	3463 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	DUNLOP	6 mm
	L/H Front Tyre	185/60 R15	DUNLOP	6 mm
	R/H Rear Tyre	185/60 R15	DUNLOP	6 mm
	L/H Rear Tyre	185/60 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/05/2022	Inspection Date	17/05/2022
	Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	