

# Kang Car Repairers Pte Ltd

I Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST: 201300201N

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623

TEL: 64616555 FAX: 62213147

ATTN: Motor Claim Department

Claim Type: Third Party  
 Accident Date: 11/05/2022  
 TP Veh Reg No: SJZ8114Y

**Estimate No:** EST2200152

Date: 13 May 2022

Veh Reg No: SNE3675R

Make/Model: HONDA FIT 1.3 HOME CVT

Chasis No: GR11105709

Reg. Date: 08/03/2022

Your Ref No: SJZ8114Y

Xiao Chen.

## Estimate Repair Cost to Vehicle No :SNE3675R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	<b>List Price</b>		
1	1 PC BOOT LID Dented	1,035.60 ✓ 958	
2	1 PC BOOTLID LOGO New	40.70 ✓	
3	1 PC BOOTLID "FIT" EMBLEM New	30.80 ✓	
4	1 PC BOOT LID LOCK Dented New	193.80 ✓	
5	1 PC BOOT LID LOCK CHECKER New	58.40 ✓	
6	1 PC BOOT LID RUBBER lot	177.40 ✓	
7	1 PC REAR WINDSCREEN RUBBER New	97.70 ✓	
8	1 PC REAR PANEL Dented	495.10 ✓	
9	1 PC REAR PANEL TRIM Dented	91.50 ✓	
10	1 PC REAR BUMPER Dented	788.30 ✓	
11	2 PCS REAR BUMPER SIDE RETAINER New	57.40 ✓	
12	1 PC REAR BUMPER REFLECTOR - RH New	99.30 ✓	
	Tools Tray Sponge 285.40 ✓	3,166.00	633.20 2.532.80
		Less 20%	
	Carb		
	<b>Special Net</b>		
13	1 PC REAR WINDSCREEN SEAL 3m	60.00 30	
14	1 PC REAR WINDSCREEN SEALANT 3m	60.00 30	
15	1 SET REAR PANEL TRIM CLIPS New	40.00 20	
16	1 SET REAR BUMPER CLIPS New	40.00 30	
17	1 SET REVERSE SENSORS Dented	350.00 200	
		550.00	550.00
	<b>Labour</b>		
18	1 TO CHECK WIRING	50.00 30	
19	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
20	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00 ✓	
21	1 TO REMOVE AND REFIT REAR VIDEO CAMERA	80.00 50	
22	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
23	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 50	

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST: 201300201N

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623  
**TEL:** 64616555      **FAX:** 62213147  
**ATTN:** Motor Claim Department

**Claim Type:** Third Party  
**Accident Date:** 11/05/2022  
**TP Veh Reg No:** SJZ8114Y

**Estimate No:** EST2200152  
**Date:** 13 May 2022  
**Veh Reg No:** SNE3675R  
**Make/Model:** HONDA FIT 1.3 HOME CVT  
**Chasis No:** GR11105709  
**Reg. Date:** 08/03/2022  
**Your Ref No:** SJZ8114Y

## Estimate Repair Cost to Vehicle No :SNE3675R

Quantity	Description	List Price	Amount
		\$	\$
24	1 TO SPRAY PANEL SEALANT	2070	100.00 65
25	1 TO REMOVE AND REFIT INNER TRIM		100.00 65
26	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.		1,000.00 850
27	1 (REAR) TO SPRAY PAINTING		1,000.00 800
		2,690.00	2,690.00
	Total		\$ \$ 5,772.80
	Add GST @ 7%		404.10
	Total Amount Payable		\$ \$ 6,176.90

**TOTAL: SINGAPORE DOLLAR SIX THOUSAND ONE HUNDRED SEVENTY SIX AND CENTS NINETY ONLY**

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Li  
 L/S 17/05/22  
 06 Days.

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4150

Supplementary: 278.80  
 Total: 3521.528  
 L/S: 4150

SNE 367SR

## Supplementary

Rees	Bumper Impact Bracket RH.	68.10.	DD
Rees	End Panel Antenna Sensor	178.20.	DM
Rees	End Panel Buzzers.	102.40.	DM
Total			348.50

Len 20%: 278.80.