



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7337C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	TO REPAIR SEE LABOUR	4,823.48	-
1	FRONT BUMPER	DENTED	1,982.37	1,435.00
2	FRONT BUMPER BRACKET	NOT DAMAGED	408.84	-
1	FRONT BUMPER FOG LAMP LH	NOT DAMAGED	384.00	-
1	FRONT BUMPER FOG LAMP GARNISH LH	NOT DAMAGED	187.00	-
1	FRONT SIDE PANEL LH	TO REPAIR SEE LABOUR	5,224.68	-
1	FRONT GRILLE	NOT DAMAGED	1,470.00	-
1	HEADLAMP LH	CUT	972.46	684.00
	LESS 25% DISCOUNT		-3,863.21	-529.75
			11,589.62	1,589.25
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	FRONT PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT SIDE PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT SIDE PANEL STICKER 'EXCURSION BUS' (SN)	NECESSARY	180.00	80.00
1	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
			510.00	80.00
	<u>LABOUR</u>			
	CHECK WIRING.	NOT NECESSARY	100.00	-
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR FRONT PANEL AND FRONT SIDE PANEL LH.		1,600.00	800.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,600.00	600.00
			3,800.00	1,400.00
	GRAND TOTAL		15,899.62	3,069.25



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00
---	--	--	----------

Report Ref No. CS/AGI22004519/Bqce2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.