

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004524/EVCE2**Date:** 02/02/2023**REFERENCE**

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD Policy No: 099999355/1220000168
Date of Loss: 10/05/2022 Nature of Claim: OD Claim No: 4934984560SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND548A**
Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM024241
Reg. Date: 30/11/2021 (Man. Year: 2020) Chassis No: WAUZZZF45LN014797
Colour: White Odometer: 11178 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$185,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm
Front Right Side: Hankook 4 mm Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	93,324.00	34,143.68	59,180.32	63.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	31,704.00	11,774.00	19,930.00	62.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	125,028.00	45,917.68	79,110.32	63.27
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	123,228.00	44,117.68	79,110.32	64.20
+ GST 8.00/8.00% (S\$)	9,858.24	3,529.41	6,328.83	64.20
Nett Amount (S\$)	133,086.24	47,647.09	85,439.15	64.20

INSPECTION

Date of Assignment: 13/05/2022
Date Inspected: 13/05/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 10.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	O/S Bent	79.00 FS	*31.60 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Broken	234.00 FS	*234.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	293.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH / RH	O/S Broken	102.00 FS	*40.08 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Not Necessary	293.00 FS	*- FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Missing	302.00 FS	*240.80 FS
9	1		*FRONT BUMPER TRIM - LH / RH	O/S Cut	108.00 FS	*42.64 FS
10	1		*RADIATOR GRILLE	Broken	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	212.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	899.00 FS	*- FS
13	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	508.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION - LH / RH	O/S Broken	82.00 FS	*32.24 FS
15	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
16	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
17	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
20	4		*FRONT BUMPER POP RIVET	Not Necessary	4.00 FS	*- FS
21	2		*HORN - LH / RH	Not Necessary	273.00 FS	*- FS
22	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	530.00 FS	*- FS
24	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
26	2		*FRONT FENDER - LH / RH	Dented	2,454.00 FS	*1,963.20 FS
27	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
28	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Necessary	162.00 FS	*128.48 FS
29	1		*FRONT FENDER BRACKET - LH / RH	O/S Necessary	82.00 FS	*32.72 FS
30	1		*FRONT FENDER BRACE - LH / RH	O/S Bent	264.00 FS	*105.20 FS
31	12		*FRONT FENDER POP RIVET	Necessary	46.00 FS	*36.48 FS
32	1		*FRONT FENDER BRACKET CENTER - LH / RH	O/S Bent	110.00 FS	*44.00 FS
33	2		*FRONT FENDER BRACKET END - LH / RH	Not Necessary	71.00 FS	*- FS
34	2		*FRONT FENDER CLOSING ELEMENT END - LH / RH	Not Necessary	74.00 FS	*- FS
35	2		*FRONT WHEEL HOUSING LINER - LH / RH	Torn	518.00 FS	*414.40 FS
36	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
37	2		*FRONT WHEEL SPOILER - LH / RH	Broken	164.00 FS	*130.24 FS
38	2		*FRONT WHEEL SPOILER LOWER - LH / RH	Missing	79.00 FS	*63.12 FS
39	1		*BONNET	Repair	3,425.00 FS	*- FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
41	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
42	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Not Necessary	93.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
44	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
45	1		*HEADLIGHT - LH / RH	O/S Cut	16,344.00 FS	*6,537.60 FS
46	2		*HEADLIGHT HOSE	Not Necessary	83.00 FS	*- FS
47	1		*SPACER (6PCS)	Missing (2Pcs Only)	270.00 FS	*71.04 FS
48	1		*LIFT CYLINDER - LH / RH	O/S Missing	462.00 FS	*184.40 FS
49	2		*LIFT CYLINDER BRACKET	Not Necessary	14.00 FS	*- FS
50	1		*LIFT CYLINDER CORRUGATED PIPE	Broken	107.00 FS	*85.60 FS
51	1		*LIFT CYLINDER CORRUGATED PIPE - UPPER	Torn	53.00 FS	*42.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*WASH WATER RESERVOIR	Not Necessary	160.00 FS	*- FS
53	1	*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
54	2	*LOCK CARRIER BRACKET - LH / RH	Not Necessary	85.00 FS	*- FS
55	6	*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
56	2	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	102.00 FS	*- FS
57	2	*RADIATOR AIR GUIDE INNER - LH / RH	Not Necessary	38.00 FS	*- FS
58	1	*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
59	1	*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
60	1	*FRONT DOOR - RH	Repair	3,431.00 FS	*- FS
61	1	*FRONT DOOR OUTER SEAL - RH	Not Necessary	229.00 FS	*- FS
62	1	*BONDING AGENT	Not Necessary	51.00 FS	*- FS
63	1	*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
64	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
65	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,153.00 FS	*- FS
66	1	*FRONT DOOR CATCH - RH	Not Necessary	116.00 FS	*- FS
67	1	*TYRE PRESSURE DATA PLATE	Not Necessary	42.00 FS	*- FS
68	2	*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	Not Necessary	688.00 FS	*- FS
69	1	*A/B PILLAR FRAME MEMBER - LH	Not Necessary	2,874.00 FS	*- FS
70	1	*FRONT DOOR SILL TRIM STRIP - LH	Not Necessary	133.00 FS	*- FS
71	3	*ALUMINIUM RIM	Bent	3,876.00 FS	*3,100.80 FS
72	4	*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
73	1	*FRONT SUBFRAME	Bent	2,096.00 FS	*1,676.80 FS
74	1	*FRONT WISHBONE LINK - LH / RH	N/s Bent	1,210.00 FS	*483.60 FS
75	1	*FRONT SUSPENSION GUIDE - LH / RH	N/s Bent	2,114.00 FS	*845.60 FS
76	1	*FRONT SUSPENSION GUIDE UPPER - LH / RH	N/s Bent	1,150.00 FS	*460.00 FS
77	1	*REAR SUSPENSION GUIDE UPPER - LH / RH (2PCS)	Bent (1Pc Only)	1,150.00 FS	*460.00 FS
78	1	*FRONT WHEEL BEARING HOUSING - LH / RH (2PCS)	Bent (1Pc Only)	2,140.00 FS	*856.00 FS
79	1	*SWIVEL JOINT (2PCS)	Bent (1Pc Only)	427.00 FS	*170.80 FS
80	1	*FRONT WHEEL BEARING WHEEL HUB (2PCS)	Necessary (1Pc Only)	995.00 FS	*398.00 FS
81	1	*DOUBLE BALL BEARING FLANGE (2PCS)	Necessary (1Pc Only)	545.00 FS	*218.00 FS
82	1	*SUSPENSION FORKS - LH / RH (2PCS)	Bent (1Pc Only)	586.00 FS	*234.00 FS
83	1	*COUPLING ROD (4PCS)	Bent (1Pc Only)	516.00 FS	*103.20 FS
84	1	*ANTI-ROLL BAR	Bent	478.00 FS	*382.40 FS
85	2	*GAS SHOCK ABSORBER	Not Necessary	664.00 FS	*- FS
86	2	*VELOCITY JOINT DRIVE SHAFT	Not Necessary	5,998.00 FS	*- FS
87	1	*STEERING GEAR TRACK ROD JOINT	Bent	7,318.00 FS	*5,854.40 FS
88	2	*TRACK ROD	Not Necessary	218.00 FS	*- FS
89	1	*TIE ROD END - LH / RH (2PCS)	Bent (1Pc Only)	434.00 FS	*173.60 FS
90	1	*SUBFRAME SUPPORT	Not Necessary	3,643.00 FS	*- FS
91	1	*WISHBONE ALUMINIUM - LOWER	Not Necessary	963.00 FS	*- FS
92	1	*WISHBONE - LH UPPER	Not Necessary	624.00 FS	*- FS
93	1	*WISHBONE - LH FRONT	Not Necessary	137.00 FS	*- FS
94	1	*WISHBONE - LH REAR	Not Necessary	501.00 FS	*- FS
95	1	*TRACK ROD - LH REAR	Not Necessary	188.00 FS	*- FS
96	1	*REAR WHEEL BEARING HOUSING - LH	Not Necessary	1,097.00 FS	*- FS
97	1	*WHEELHUB BEARING	Not Necessary	723.00 FS	*- FS
98	1	*WHEEL BEARING HOUSING STONE CHIP GUARD	Cut	49.00 FS	*39.20 FS
99	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
100	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
101	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
102	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
103	1	*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
104	1	*RHS FRONT TYRE	Torn	320.00 FS	*320.00 FS
105	1	*LHS FRONT TYRE	Torn	320.00 FS	*320.00 FS
106	1	*LHS REAR TYRE	Torn	320.00 FS	*320.00 FS
107	1	*SUNDRIES	Necessary	1,000.00 FS	*345.28 FS
108	1	*FRONT NOISE INSULATION (Supplementary)	Broken	437.00 FS	*349.60 FS
109	1	*UNDERBODY TRIM-LH/RH (2pcs) (Supplementary)	Broken	751.00 FS	*600.80 FS
110	1	*UNDERBODY TRIM-FRONT RH (Supplementary)	Broken	51.00 FS	*40.80 FS
111	1	*FUEL LINE (Supplementary)	Torn	442.00 FS	*353.60 FS
112	1	*CENTRE SILENCER (Supplementary)	Dented	956.00 FS	*764.40 FS
113	1	*DUAL CLIP-55MM (2pcs) (Supplementary)	Necessary	120.00 FS	*95.84 FS
114	1	*DUAL CLIP-65MM (Supplementary)	Necessary	68.00 FS	*53.92 FS
115	1	*SILENCER BRACKET-INNER (Supplementary)	Necessary	22.00 FS	*17.52 FS
116	1	*SILENCER BRACKET-OUTER (Supplementary)	Necessary	53.00 FS	*42.00 FS
117	1	*FRONT FENDER LEDGE COVER-LH/RH (2pcs) (Supplementary)	Broken	70.00 FS	*55.04 FS
118	1	*HEADLIGHT COVER-LH/RH (2pcs) (Supplementary)	Broken	98.00 FS	*77.28 FS
119	1	*REAR BUMPER SPOILER (Supplementary)	Cut	276.00 FS	*220.80 FS
120	1	*REAR SILENCER HEAT SHIELD (Supplementary)	Dented	76.00 FS	*60.72 FS
121	1	*FRONT NOISE INSULATION	Broken	640.00 FS	*512.00 FS
				Total Parts (S\$)	93,324.00 34,143.68

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	250.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
4	TO REMOVE AND REINSTALL LHS FRONT PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
5	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
6	TO REMOVE AND RENEW BOTH FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
7	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
8	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	0.00
9	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET, RHS FRONT DOOR AND BOTH HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS LOWER A-PILLAR WITH LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-IRGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	10,000.00	2,000.00
10	TO RESPRAY FRONT BUMPER, BONNET HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS, RHS FRONT FENDER TOP SUPPORT, LHS A-PILLAR, LHS SILL PANEL AND DOOR ENTRANCE	New	8,000.00	3,300.00
11	TO RENEW RHS FRONT RIM WITH TYRE, LHS FRONT RIM WITH TYRE AND LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	560.00
12	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
13	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
14	TO REMOVE AND RENEW CENTER EXHAUST SILENCER AND ALIGN TO POSITION. (Supplementary)	New	480.00	480.00
15	TO RENEW FUEL LINE. (Supplementary)	New	780.00	780.00
16	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. (Supplementary)	New	360.00	360.00
17	TO REMOVE AND REINSTALL REAR BUMPER.TO RENEW REAR LOWER SPOILER. (Supplementary)	New	1,050.00	500.00
Gross Labour Cost (\$\$)			31,704.00	11,774.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >