

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Rizal, Nur Mariah Huibrechts

Date: 16 May 2022

Preliminary Advice

Vehicle No	: SND548A	Accident Date	: 10/05/2022
Make	: AUDI A4	Policy No.	: 099999355/1220000168
Assignment Date	: 13/05/2022	Excess	: S\$0.00
Date of Inspection	: 13/05/2022	Est. Duration of Repair	: 10
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	108,963.00
Revised Amount	:S\$	29,152.25
Check Items (Estimated)	:S\$	51,840.00
Total	:S\$	80,992.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	240,013.00
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	109,554.00
Salvage Value	:S\$	
Margin for Repair (New for old Value)	:S\$	130,459.00
Margin for Repair (Pre-accident Value)	:S\$	75,446.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the margin of repair (Pre-Accident Value) is \$75,446.00 and Margin for Repair (New for Old Value) is 130,459.00