

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22004534/EPA3Q2**Date:** 20/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SMR4084H **Insured Vehicle No :** SLT6139Y
 Date of Loss: 06/05/2022 Nature of Claim: TP Claim No: MFL2022D0002309

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR4084H**
 Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 CVT (A) Engine No: 4B40GY7479
 Reg. Date: 03/01/2020 (Man. Year: 2019) Chassis No: JMAXTGK1WKZ001917
 Colour: Brown Odometer: 15543 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,575.00	4,503.00	72.00	1.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,710.00	1,410.00	45.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,695.00	6,213.00	1,482.00	19.26
+ GST 7.00/7.00% (S\$)	538.65	434.91	103.74	19.26
Nett Amount (S\$)	8,233.65	6,647.91	1,585.74	19.26
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,615.36		
Global Sum Settlement (S\$)		7,600.00		

INSPECTION

Date of Assignment: 13/05/2022
 Date Inspected: 09/06/2022 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2022)
Parts:	143	MITSUBISHI ECLIPSE CROSS 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR4084H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FACE ,FR BUMPER	Crushed	990.00 FS	*990.00 FS
3	1		*COVER ,FR BUMPER	Cut	382.00 FS	*382.00 FS
4	1		*GARNISH ,FR BUMPER SIDE	Broken	295.00 FS	*295.00 FS
5	1		*EXTENSION ,FR BUMPER (SPOILER CENTRE FRONT)	Necessary	318.00 FS	*318.00 FS
6	1		*BRKT ,F/BMPR T/SIG LAMP ,RH	Not Necessary	17.00 FS	*- FS
7	1		*BRACKET ,FR BUMPER SIDE ,RH	Not Necessary	25.00 FS	*- FS
8	1		*HEADLAMP ASSY ,RH	Broken	2,498.00 FS	*2,498.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,575.00** **4,503.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER PANEL & AFFECTED AREA	New	1,280.00	640.00
2	PAINT WORK ON FRONT BUMPER PANEL	New	1,100.00	550.00
3	REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR	New	180.00	160.00
4	TO APPLY SEALANT ON AFFECTED AREA	New	100.00	0.00
5	PERFORM RUST PREVENTION	New	50.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	80.00	80.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
8	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	0.00
Gross Labour Cost (S\$)			3,120.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >