

Vehicle Damage Assessment Report for [SMR4084H]

Estimate Created: 14/05/2022 14:51 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 17/09/2022 14:12 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mitsubishi	Model	Eclipse Cross
Engine Type			
License Plate Number	SMR4084H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provided by AIS: Concluded the cost of repair at part by part \$6,213 with 3 days for repair

Insurlogic 3 (17/09/2022 14:12)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Face,Front Bumper		1	990.00	0.00 %	990.00
Cover,Front Bumper		1	382.00	0.00 %	382.00
Garnish,Front Bumper Side		1	295.00	0.00 %	295.00
Spoiler Centre Front		1	318.00	0.00 %	318.00
Headlamp Assy RH		1	2498.00	0.00 %	2,498.00

Parts Subtotal 4,483.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Sundries		1.0	20.00	0.00 %	20.00

Materials Subtotal 20.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove & refix front damaged parts	RnR	640.00	0.00 %	640.00
Remove & install front parking assist for facilitate repair	RnR	160.00	0.00 %	160.00
Check wiring	RnR	80.00	0.00 %	80.00
Diagnostic	RnR	280.00	0.00 %	280.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray paint on the front affected area	Full spray	550.00	0.00 %	550.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,160.00

Paint Labor Subtotal 550.00

Labor Subtotal 1,710.00

Summary

Repair Cost 6,213.00

Discount(0 %) (0.00)

6,213.00

Excess (0.00)

GST(0.00 %)	0.00
Grand Subtotal	6,213.00