



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NGO MIN YING	Cust No/Name /NGO MIN YING
24 MOONBEAM VIEW	Reg No/Reg Date SMR4084H / 03/01/202
SINGAPORE 277278	Date In/Mileage / 0
Contact No Mobile: 91546268	Chassis No JMAXTGK1WKZ001917
	Engine No 4B40GY7479
	Make/Model MIT/ECLIPSE CROSS 1.5 STYLE SR (T23
	Colour/Trim CO2 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	07/05/2022/ 11:15	TLK	282 / Kevin Leong	23083		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1280.00
REPLACE FRONT BUMPER PANEL & AFFECTED AREA				640 x 1			
E PNT98000							1100.00
PAINT WORK ON FRONT BUMPER PANEL				550 x 1			
E PNT88000							180.00
REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR							
M SUNDRY							X 100.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							X 50.00
PERFORM RUST PREVENTION							
A 54900099							80.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							X 50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME							
M SUNDRY							20 50.00
SUNDRIES							
M FACE,FR BUMPER				1.00	990.00	00.00	990.00
M COVER,FR BUMPER				1.00	382.00	00.00	382.00
M GARNISH,FR BUMPER SIDE				1.00	295.00	00.00	295.00
M EXTENSION,FR BUMPER				1.00	318.00	00.00	318.00
M BRKT,F/BMPR T/SIG LAMP,RH				1.00	17.00	00.00	17.00
M BRACKET,FR BUMPER SIDE,RH				1.00	25.00	00.00	25.00

CR4

CUT (BLACK)

(CR4) - BR

X

?

?

Steve (LKK)

9/6/22, 1.00pm

W PL

P/P

by PL by

3 by

Steve (LKK)
9/6/22, 1:00pm

MR PL
P/P
by PL
3 days

LKK Auto Consultants hence notify
Confirm & accepted by
the Receiver of the following:
• To resurvey & repair after spray painting
• To display damaged part showing resurvey
• Parts price based on "no prejudice" basis
• Third party survey is allowed
• No illegal modification is allowed
• Supplementary items must be resurveyed and
Authorized signatory and company stamp

7% GST on
Total Payable

Nett 5,197.00
363.79
5,560.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.