



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|--|
| NGO MIN YING | Cust No/Name /NGO MIN YING |
| 24 MOONBEAM VIEW | Reg No/Reg Date SMR4084H / 03/01/202 |
| SINGAPORE 277278 | Date In/Mileage / 0 |
| Contact No Mobile: 91546268 | Chassis No JMAXTGK1WKZ001917 |
| | Engine No 4B40GY7479 |
| | Make/Model MIT/ECLIPSE CROSS 1.5 STYLE SR (T23 |
| | Colour/Trim CO2 BRONZE METALLIC/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---|-------------------|-----|-------------------|------------|--------|--------|---------|
| CSM00041 | Cash | 07/05/2022/ 11:15 | TLK | 282 / Kevin Leong | 23083 | | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount | |
| E PNT88000 | REPLACE FRONT BUMPER PANEL & AFFECTED AREA | | | | | | | 1280.00 |
| E PNT98000 | PAINT WORK ON FRONT BUMPER PANEL | | | | | | | 1100.00 |
| E PNT88000 | REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR | | | | | | | 180.00 |
| M SUNDRY | TO APPLY SEALANT ON AFFECTED AREA | | | | | | | 100.00 |
| M SUNDRY | PERFORM RUST PREVENTION | | | | | | | 50.00 |
| A 54900099 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | 80.00 |
| A 10028901 | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | 280.00 |
| M SUNDRY | TO SUPPLY FRT NUMBER PLATE WITH FRAME | | | | | | | 50.00 |
| M SUNDRY | SUNDRIES | | | | | | | 50.00 |
| M FACE,FR BUMPER | | | | | 1.00 | 990.00 | 00.00 | 990.00 |
| M COVER,FR BUMPER | | | | | 1.00 | 382.00 | 00.00 | 382.00 |
| M GARNISH,FR BUMPER SIDE | | | | | 1.00 | 295.00 | 00.00 | 295.00 |
| M EXTENSION,FR BUMPER | | | | | 1.00 | 318.00 | 00.00 | 318.00 |
| M BRKT,F/BMPR T/SIG LAMP,RH | | | | | 1.00 | 17.00 | 00.00 | 17.00 |
| M BRACKET,FR BUMPER SIDE,RH | | | | | 1.00 | 25.00 | 00.00 | 25.00 |

Confirm & accepted by

7% GST on **5,197.00** **363.79**
Nett 5,197.00
Total Payable 5,560.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.